DEC 1 5 1998

4. Lot No.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office	
Resister's Office County	68

	Received			
25	day	01 No	OVEM.	Ben
A. D.	19 <i>76</i> at	10:0	<u>∂</u> o'cl	ock
A	n.,	and re	corded	in
W 74	~7	-56	a 2 416	
m pag	e 87 onu (d R			
Ram	ona Col	lim.	Dip	uly
	R	egistor	of D	eeds "

Register of Deeds Stamp & File Number

For	corners in ECTION		
G	logebic (County)	Located In:	Corner Code ##
1.	Public Land Survey	146N R 45W	A-10
		T <u>R 46N</u> R 46W	M-10
2.	Property Controlling in Section	S T R S T R	
3.	Miscellaneous Property in Sec.	S T R S T R	

5. Private Claims _____

½ Corner 30 & 25; T.46 N., R.45-46 W.

___ , Recorded Plat _

i, <u>Richard L. Drahn</u>in a field survey on <u>November 3</u>, 19 <u>98</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by John Burt on 9/1/1847. Original B.T.s ---Cedar 6" S.15 E. 20 links (13.20') --- 8" Cedar N.80 W. 8 links (8.28') ---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record bearing and distance from the remains of the two original B.T.s. The first is a badly decayed 8-12" Cedar with portions of both blaze faces and overgrowth still evident. the second one is now a very badly decayed 10-12" downed Cedar.

Corner research on file with Gogebic County records.

Reduce & Drahm 11/24/90

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 3/4" X 4' aluminum rod with a $3\frac{1}{4}$ " stamped aluminum cap and the following new B.T.s:

10"	Cedar	N.09 W.	33.28'
8"	Hemlock	S.37 E.	28.53'
9"	Cedar	N.70 E.	15.17'
6'	Steel sign rail	s.65 W.	2.44'

Signed by Richard L. Drah Date November 9, 1998

Surveyor's Michigan License No. 21564

USFS T-1

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN... 1983

RICHARD L. DRAHN LAND SURVEYOR No. 21564