## SUMVEY & REMONUMENTATION

AUG 0 8 1997

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office	
Register's Office Gogebic County	/

For	corners	in		

Miscellaneous

Property in Sec.

	Gogebic (County)	Located In:	Corner Code ##	
1.	Public Land Survey	т <u>46N в 45W</u>	G-9	
		T R		
		T R		
		T R		
2.	Property Controlling	S T R	·	
	in Section	S T R		

R

U	Ron	ic (,	UURE	j		
		R	eceive	d for	record	the
	9	724	da	y of	APRIL	٤
					<i>:45</i> 9°€	
					recorde	

OL CORNER

Register of Deeds Stamp & File Number

4.	Lot No.	, Recorded Plat

Section Corner 21, 22, 27 & 28; T.46 N., R.45 W

Richard L. Drahn in a field survey on November 4. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	<u> </u>	₿	c	0	E	F	G	H (	J	K	Ł	M
2	_	6—		5—		4-	_ ;	3—		2 —		
3		<u> </u>		L.		_	<u> </u>					-
4	_	ļ 7—		 B	L	ļ —	1		1	1	1	2
5		_	-	_		<u> </u> _	_					
6	1	  8	1	ا 7—	L,	6	ļ.,	5	1	4—	1	3
7	<u>_</u>	_	L				_					
8	1	9	2	<u> </u>	_2		_2	2	2	3	2	4_
9						L.,,	<u> </u>	L				
10	3	 	2	9	2	8—	2	7_	2	6-	ź	5
11		L			L							
12	3	1	3	2	_3	3	3	4	3	5	3	6—
13		<u> </u>		_	L	<u></u>						L

A. Description of original monument and accessories and/or subsequent restoration:

Original B.T.s --- Y. Birch Corner established by Austin Burt on 8/2/1851. 24" S.73 W. 45 links (29.70') --- Cedar 12" N.33 E. 49 links (32.34') ---1960 State Hiway Plans indicate the corner marked by a 12" iron pipe. B.T.s set in 1960: --- 4" Maple N.40 W. 8.78' --- 8" Maple South 11.01' ---6" Maple N.25 E. 10.92'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner position found marked by a  $1\frac{1}{2}$ " iron pipe with a  $2\frac{1}{4}$ " brass cap by NORTHERN PAPER MILLS stamped 21, 22, 27, & 28. (No name or date) at record bearing and distance from the decayed remains of the original Y. Birch No evidence remains of the original Cedar B.T. bearing tree.

Recovered the States 1960 B.T.s as: 7" Sugar Maple with MSHD brass washer N.40 W. 8.78'; 15" Sugar Maple South 11.01'; 11" Sugar Maple N.29 E. 10.92'.

4" scribed Cedar post bears N.11 W. 0.5'.

REFULSELLIATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

At the location of the brass capped iron pipe I set a 2" dia. by 30" long aluminum monument with a 31/4" alum. cap stamped: COUNTY REMONUMENTATION; T.46 N., R.45 W.; S-21, S-22, S-27, S-28; 1996; RLS 21564; 1996. I blazed and scribed and placed B.T. tags on the MSHD B.T.s. 31. 10

New bearing object referenced:

6' Steel sign rail S.60 E. 2.16'

> 21564 998mm Million \_ Date <u>November</u>

Surveyor's Michigan License No. \_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

RICHARD L. URAHN

LAND SURVEYOR

21564