AUG U 8 1997

COMMISSION

4. Lot No. . 5. Private Claims _

LAND CORNER RECORDATION CERTIFICATE Gogebic County

Register's Office

_	Filing Require	ment of Act 74, Mich. P.A. 193	70 Received for record that
For corners in			4th day of April
Gogebic (County)	Located In:	Corner Code ##	A. D. 19 17 at 10:45 o'clock
Public Land Survey	T 46N R 45W	G-11	A m., and recorded in
	T R T R T R		e chad Brown
Property Controlling in Section	STR STR		Register of Doeds CA
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No ,	Recorded Plat		— ABCDEFGHIJKL

Section Corner 27, 28, 33 & 34: T.46 N., R.45 W.

Richard L. Drahn in a field survey on November do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

3 10 12

A. Description of original monument and accessories and/or subsequent restoration:

Original B.T.s --- Sugar 10" Corner established by Austin Burt on 8/2/1851. S.58 E. 12 links (7.92') --- Sugar 8" N.53 W. 20 links (13.20') ---

1960 State Hiway Plans indicate the corner marked by a 4" squared post. New B.T.s set in 1960: --- 5" Birch S.35 W. 17.75' --- 3" Birch S.85 E. 7.40' --- 6" Maple N.10 W. 16.55'---

William Stuth, Wisc. RLS found corner marked by an iron pipe and a wood post in 1984.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original bearing trees destroyed by logging and road construction. Corner position found marked by a 2½" X 2.6' iron pipe. Recovered the States 1960 B.T.s as: dead and down Y. Birch bearing S.46 W. app. 17.8', recover the brass MSHD washer --- no evidence remains of the Birch at S.85 E. --- 11" live Sugar Maple with 1960 brass MSHD washer at N.10 W., 16.55'

Scribed 3" sq. Cedar post bears S.46 E. 0.6'

3/4" dia. iron pipe bears S.08 E. 0.5'

Due to this corners long usage I accepted its' location as best representing the point set by Austin Burt in 1851.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner; At the location of the 2¼" iron pipe I set a 2" dia by 30" long diament with a 3¼" Alum. cap stamped: COUNTY REMONUMENTATION T. 46 N., R.45 W.: S-27, S-28, S-33, S-34: RLS 21564: 1996. From which Isserbathe At the location of the $2\frac{1}{4}$ " iron pipe I set a 2" dia by 30" long aluminum monument with a 3½" Alum. cap stamped: COUNTY REMONORED R. 45 W.: S-27, S-28, S-33, S-34: RLS 21564: 1996. From which rimes are property of the state of the stat

owing	new B.T.S		L.
6'	Steel sign rail	N.57 W.	1.74'
9"	Sugar Maple	N.15 E.	20.66'
8"	Sugar Maple	S.07 E.	37.89'
10"	Sugar Maple	s.65 W.	36.18'

November Date ...

Surveyor's Michigan License No. 21564