LAND CORNER RECORDATION CERTIFICATE

Beginter's infice

Filing Requirement of Act 74, Mich. P.A. 19		970 Received for record the					
Gogebic (County)	_ Located In:	Corner Code #	A. D. 19 a	A. D. 1900 at 1:20 o'clock			
1. Public Land Survey	T46 N R <u>46 W.</u> T R T R	E-12	Liber 7 m page 3 Chery	ol	CORNILE C. De		
Property Controlling in Section Miscellaneous Property in Sec.	T R S T R T S T R S T R S T R		Register of Dec	K eginter eds Stamp 8	of Dool	ber	
4. Lot No, Rec 5. Private Claims	orded Plat	SECTION	A B C D E	F G H	1 J K	L A	
Quarter Corner 32 & 33; T.46 N., R.46 W.			3	4 3	2-	-1- -	
that under requirements of P. lines 1 and 2 above were in a the current manual of survey Bureau of Land Managemen	A. 74, Michigan P.A. of 19 conformance with regulation instructions of the United at or by a decree of a Cou	do hereby state 70, the corner points mentioned in s and rules therefore as required in States Department of the Interior, rt of Law and /or that the corner	4 7 8 5 6 18 17 7 7	9 -10-	11-	-13-	
•	urveyors or by a Decree	onformance with the rules of the of a Court of Law; established, sed below:	8 19 20 9 10 30 29	-21 - 22 	23	-2 4	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			11 32 32	_3334	35	_ _36	
A. Description of original me	onument and accessories ar	nd/or subsequent restoration:	13		· · · · · · · · · · · · · · · · · · ·		

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner established by Austin Burt on 7/9/1851. Original bearing trees:

S.27° E.

N.38° W.

I restored the corner position at record bearing and distance from the remains of the original Hemlock bearing tree. It is now a very badly decayed Hemlock stump with Hemlock roots, bark and wood. This is the only old growth hemlock remains recovered at this latitude. No evidence remains of the original Fir bearing tree.

(21.78')

(16.50)

A maple picket with blazed and painted and/or ribboned lines running north, south and west; bears S.80° E., 64 feet from the original corner location.

Corner research on file with Gogebic County records.

10"

10"

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

33 links

25 link

At the corner position I set a 3/4" X 4' aluminum rod monument with a 3 1/4" stamped aluminum cap and the Following new B.T.s (all measurements taken to a nail in side of tree):

Red Maple Red Maple

Surveyor's Michigan License No.

Fir

Hemlock

N.40° E.

6.46 32.27

Sugar Maple

6"

21564

S.26° W. S.63° E. 5" Steel sign rail N.72° W.

30.04 1.92'

Date __June 14, 2000

FORM APPROVED BY MICHIGAN STATE BOAR!) OF PROFESSIONAL SURVEYORS, JAN. 28,

REVISED MAY 14,1976 REVISED JAN., 1983 REVISED OCT., 1995

LAND

RICHARD

L. DRAHN

LAND

SURVEYOR No. 21564

A.F.

USFS X-9