MAR 0.2 2000

ú

איייי לי לי לי לי		r.
SECTION For corners in	LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 19	970
ONTONAGON Located in	1: Corner Code #	Received for record the 1074 day of November A. D. 19 99
GOGEBIC (County)	509.2	
4 44 14 4	48N R 41W E-13	A clock
	47N R 41W E=1	Liber 7 and recorded in
· (R	O VORNEDI
T	R	page 2.72
2. Property Controlling S T in Section S T	R	Romana Collins Deput
3. Miscellaneous S T	R	Register of Bonds
Property in Sec. S T	K	- pode
nii		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims		A B C D E F G H I J K L
Section Corner common to a	20.4.20	
•	ections 32 & 33, T48N R41W &	3 1 1 1 1 1 1 1 1
	vey on Oct. 01, 19 99 do hereby state that under	3
requirements of P.A. 74, Michigan P.A. of 1970,	the corner points mentioned in lines 1 and 2 above were in	4 7 10 11 11 12
United States Department of the Interior Pureaus	required in the current manual of survey instructions of the	5
that the corner points mentioned in lines 3, 4 and	Sabove week in conformance with the rules of the Michigan	6 18 17 16 15 14 13
recovered, found as expressed below:	Court of Law; established, re-established, monumented,	7
		8 19 20 21 22 23 24
NOTE: Not more than 2 comers, all in the sal	me town and range; may be recorded	9
on this certificate.		10 30 29 28 27 36 35
! *		20 7 7 20 7 20 7 23
,		11
		12 31 32 33 34 35 36
A. Description of original monument and acc	essories and/or subsequent restoration:	
Original corner established Deputy Surveyor in 1847. S	by William A Burt II c	
ORIGINAL BEARING TREES:		
Hemlock 14" N35°E	4 * inh 12 c4 c	Drun coore
	4 Links (2.64 feet)	PREER CHOUP APPROVED
1103 W	18 Links (11.88 feet)	sail W Epplekans
P. Donovinskov of a sur		Sail W apple and
b. Description of corner evidence found and	or method applied in restoring or reestablishing corner	r: 10-14-99
South & Corner of Section 32	vidence was found. Corner was re-e sure and on the Town Line between t 2 and the Southeast Corner of Secti	he monumented on 33.
Research on file with the Or	ntonagon County Remonumentation Pro	cream Domestics 1
•		yram m epresentative.
•	·	
C. Description of monument for corner and acc	cessories established to perpetuate locating the positio	Manual Property of the Control of th
At the corner position I and	o 1 line at the position	on of the corner:
	a $2\frac{1}{2}$ "X30" split base aluminum pipenty Remonumentation, T48N, T47N, R40. I established 3 bearing trees a	11W. SS33.
Nail in 8" Soft Maple S45°W Nail in 7" Soft Maple N74°W	39.82' - Nail in 6" S. Maple N56° 48.62' - 6' Steel Sign Post North	PROFESSIONAL SURVEYOR ON NO. 17610 10.56
& new n	4	
Signed by Kail W apple	kaup	
Surveyor's Michigan License No.	Odie	per 4, 1999
A CONTRACT LICENSE (40.	17610	