SURVEY & REMONUMENTATION

SEP 0 8 1998

, SECTION	LAND COF	LAND CORNER RECORDATION CERTIFICATE			r = laffice ss.	
For corners in		quirement of Act 74		O Gogebie	c santy) Keceived for	ropord the
On make a	and at Inc.	0		20	day of.	AUGUST
(County)	eated In:	Corner Code#			19 <i>98</i> at 1.	
1. Public Land Survey	047NR 43W	A-11)		<u> </u>	m., and	recorded in
· · · · · · · · · · · · · · · · · · ·	147NR 44W	M-11	1		of.	CORNERS
	TR TR			pag	e 47	.000
2. Property Controlling S in Section S	TRTR			ROM	1000 Collin Regist	er of Deede
3. Miscellaneous S_	_ 				J	
Property in Sec. S	_ TR			Register of I	Deeds Stamp &	File Number
A ladde December 191	•					
4. Lot No, Recorded Place 5. Private Claims	at			A B C D	EFGH	IJKLM
Section corner commo			<u>*** 31</u>	2 6 5-		
				3		
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or					9-10-	11-12-
					16-15-	14 12
that the corner points mentioned in lines 3 Board of Land Surveyors or by a Decre	3, 4 and 5 above were in	conformance with the rul	es of the Michigan	7		
recovered, found as expressed below:	·		,,	8 -19 20	21 22	23 24
NOTE: Not more than 2 corners, all in on this certificate.	n the same town and r	ange, may be recorded		9		
on this certificate.				10 30 29	28 27	26 25
				12 31 32	33 34	35 36
.				13		
A. Description of original monument Corner established by	and accessories and Dy Austin Bu	/or subsequent restora .rt. U.S. Dep	ation: Outy Survey	or, in 18	4.7•	
Corner established boriginal bearing tre	es: Y. Birc	h 7" S 560	E 17 link	s } Aust	in Burt'	s B.T.
	S. Mapi	e 12" N 67° e 10" N 67°	W 38 link E 17 link	ייי (S S) איייי		- D #
On Trans E 1073 man	Y. Birc	e 10" N 670 h 30" 580	E 17 link	s Willi	am Burt	3 B.T.
On June 5, 1971, Donald D. Lappala, RLS, USFS, restored corner position at record bearing and distance from the remains of the original bearing trees:						
He set a 22" I.D. Iron pipe with 3" Circular bronze tablet which reads: T.47 N.						
R.43-44 W.; S-25, S-	-36, S-30, S	-31; R.L.S.	12585; 197.	l. He est	ablished	the
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: following reference objec 6" Sugar Maple S 81° E 39.2"; 8" Sugar Maple S 35° E 29.7"						
4" Yellow Firch S.050 W 25.8' (down); 4"x4" Cedar sign Post N 580 E 3.5' (down) In 1985 a 5" Sugar Maple S 100 E 38.4' was added.						
He recorded said cor	maple S 10°. Ther in Fore	E 38.4' was st Service I	added. iber V-25 :	on August	10, 197	2.
Found Monument and w			_	_	•	
I updated the monume	ent and acce	ssories as n	oted below	to state	and cour	ity
specification.	2110	PEER	P.Deam BI	Maye		·
Act 74 research on f	TTe.		114-11			
C. Description of monument for corne	er and accessories es		e locating the position	· · · · ·		
From found monument	I establish	ed the follo	wing exist	ing and n	ew refer	ence
objects: 8" Sugar Maple S 8	39.2	21			September 10 F M	AMANANA I
9" Sugar Maple S 3 8" Hemlock N 4 6" Sugar Maple S 1	350 E 29.8	61				ICHICAN IN
6" Sugar Maple S 1	,40 W 27.6 LOO E 38.2	٠ 4.			JOHN GOS	_ * * */
6' Rail & Sign Due	3 S. 1.9	o, to lace			* LANI SURVEY	
(All measurements are	taken to n	ail in side	of tree)	1	No. 2350	15
					THE TAN	O'SURY STATE
Signed by John P Store	22		Date July	29, 1998	MINIM	Militar
Signed by Gohn P Sos Surveyor's Michigan License No	2350	9				···

U.S.F.S. No. V-25