AUG 0 8 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Gogebic	Office County	25.		
į	lectived	for	record	1
1124	day	of_	JUM	4
A D. 19	97 at	10.	4500	ł

10. 19 97 at 10.23 o'clock

4 m, and recorded in

15 of Corners

Colleen M. Kirkek Opaile Register of Deeds


Register of Deeds Stamp & File Number

I, John P. Goss in a field survey on June 2, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan

Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,

recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Austin Burt on Sept. 1, 1847. Set Sugar post.

Original bearing trees: Sugar 22" S 24° E 23 links Elm 16" S 742°W 25 links

on July 7, 1986, Richard Drahn RLS, restored corner position at record bearing and distance from stump holes of the two original bearing trees. Corner position verified by retracement measurement North and South from corner to recovered natural feature ties. He set a 2" I.D. iron pipe with 3" Circular brass cap, stamped to indicated the corner position. He established the following reference objects: 15" S. Maple - N 04° E - 15.35'; 7" S. Maple - S 18° E -36.90';

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

6" S. Maple - S 76° W - 27.40'; 6' Metal Sign Post - N 31° E - 2.8'.

No original evedence could be found.

Found R. Drahn 2" I.D. iron pipe with 3" circular brass cap. It checked with R. Drahn witnesses. I updated the accessories as noted below to state and county specification.

Act 74 research on file.

Rider L. Drahn 6/10/97
COUNTY BEFORE TAILYS

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the 2" I.D. iron pipe with 3" brass comp marked: T.47 N., R.44-45 W.; S-7, S-12; 1/4; 1986; R.L.S. 21564. I established the existing and new bearing

trees and reference objects.

18" Sugar Maple N 04° E 15.35'

10" Sugar Maple S 18° E 36.90' 8" Sugar Maple S 76° W 27.40'

8" Sugar Maple S 76° W 27.40!
6' Metal Sign Post N 31° E 2.8' (to face of post)
6' Rail & Sign N 70° W 2.5' (to face of post)

(measurement to nail in side of tree)

Signed by Ahm P Noss

Surveyor's Michigan License No. 23509

Date June 4, 1997

JOHN P.
GOSS
LAND
SURVEYOR
NO.
23509

Fed. No. G-25