## REMONUMENTATION

AHG fi e 1007

	Keyis	tor's	0.00	١			
COMPAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	Soge	bic (	Office ounty	88.			
For corners in		R	eceives	for	reco	rd th	10
Gogebic Located In: Corner Code #		3 1	day				_
(County)	A. D	. 19_	77_at				故
1. Public Land Survey T47NR 44W A- 10		_	m.,				
T47NR 45W M- 10	Liber						
<u></u>		, <del></del>	122				
2. Property Controlling STR			a Or	llia	10 N	مدر	atı
in Section S TR	<u> </u>					Door	
3. Miscellaneous S TR				•			
Property in Sec. S TR	Registe	r of D	eds S	tamp	& File	e Nun	nber
4. Lot No, Recorded Plat	вс	D I	Z F	G H	I	J K	L
5. Private Claims	_	5	   4	<u></u>	$\perp$	2	l l -
1/4 cor. comm. to sec's 25 & 30						1-1	
I, John P. Goss , in a field survey on May 5 , 1997 do hereby state that under	-7-	_ l 8	   9	1-10		11	—12-
requirements of P & 74 Michigan P A of 1970, the corner points mentioned in lines 1 and 2 above were in						-	
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	-18	17	  16	15	;	14	13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan  Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,						1-1	
recovered, found as expressed below:	1,9	20	—2 <u>1</u> —	-2	<del>-</del>	23	2 <sup>1</sup> 4
NOTE: Not more than 2 corners, all in the same town and range, may be recorded					- -		
on this certificate.	-30	—2 <sup>1</sup> 9—	28-	2	/ <del>-</del>	26-	—25- I
11	$\dashv$	$\dashv$		<del> </del>		1	+
12	<u>-31</u>	32	33	<del>  3</del>	1	35	—36- 
Donald Lappala, RLS, set a 5/8 inch dia. iron pin in ce record distance \( \frac{1}{4} \) mile north and south from recovered s recorded this corner in Forest Service Records in Regis Gogebic County. He established the following corner acc Power Pole No. 25-96/53 - S 52° W - 41.0'; 5" Elm - N 5 7" Elm - S 86° E - 31.5'; At a point 23.85' East of cor B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: \( 2\frac{1}{2}\)" inch dia. by 5 foot long concrete filled, galvanize circular bronze tablet which read T.47 N.; R.44-45 W.; 23.85' west; R.L.S. 12585; 1970.  Found the reference monument and bearing trees as described above, I updated Accessories as noted below to state and county specification.	ecti ter esso 7° E ner d pi	clin of orie pos pe	e of corn Deed s: 38.5 itio with , S-	ers s (	inc R.	e et h M.;	for
Act 74 research on file.  C. Description of monument for corner and accessories established to perpetuate locating the position	SOUL	∭ <sub>-z</sub> s <b>xx</b> corner	ella Berrai	<u>5</u>	12/	77	-
I placed a P.N. Nail in Bit. Surface at corner position following references objects.  P.Pole 25-96/53 S 52° W 41.04' 6" Elm (dead) N 57° E 38.54' 7" Elm (dead) S 86° E 31.47' 11" Maple S 38° E 60.00' R.M. (Lappala) East 23.85' & 6' rail & sign I set a reference monument consisting of 2½" by 30" Aluminum pipe and 3½" Aluminum cap stamped to indicate corner position.	1.4'	d es	tab his	ME JOG SU	HN OSS LAND RVEYO No.	HIGAN P.	e *** 00 m
R.M. (Goss) N 580 W 41.70' & 6' rail & sign Signed by John Surveyor's Michigan License No. 23509	199	2		.411	TVM	We.	

Fed. No. T-25