SURVEY & REMONUMENTATION

AUG Ü 8 1997

| MMCO | ISSION LAND | CORNER RECORDA | TION CERTIFICAT | re Register's Co | | |
|--|---|--|--|--|---|---|
| For corners in | \$_1111 p | B Kedmenien of Not | | - | ceived for re | cord the |
| Gogebic | Located In: | Corner Code # | | 13-2 | day of <u>\</u> | AY |
| (County) | | | | A D. 19.5 | 17 212:10 | _o'ckek |
| 1. Public Land Survey | T <u>46NR</u> (T <u>47NR</u> T <u>46N</u> R T47NR | | | Liber 6 | 125 | porded in |
| Property Controlling in Section Miscellaneous | S TR S TR S TR | | | Pamen | a Collins. Register | of Doods |
| Property in Sec. | S TR_ | | - | Register of D | eeds Stamp & | File Number |
| 4. Lot No, Record | led Plat | | | 1 B C D | E F G H | I J K L M |
| Sec. cor, comm. | | | | 3 - 6 - 5 - 3 | | |
| requirements of P.A. 74, Michiga conformance with regulations and United States Department of the lithat the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be | n P.A. of 1970, the controlles therefore as requirenterior, Bureau of Land Nin lines 3, 4 and 5 above a Decree of a Court of low: | ed in the current manual of sur Management or by a decree of were in conformance with the of Law; established, re-estab | vey instructions of the a Court of Law and /or rules of the Michigan olished, monumented, | 4 | 91015 | 11 12 13 13 14 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15 |
| NOTE: Not more than 2 com on this certificate. | ers, all in the same tow | vn and range, may be record | ded | 9 10 30 29 11 12 31 32- | 33 34 | 26 - 25 - 1 - 35 - 36 - 1 - 36 - 1 |
| A Description of original monoriginal corner Original bearing on October 1, 1 bearing and distable which real He recorded said Deeds Office for blazed and scrible Description of corner eving 17° W - 17° 4° In 1985 a 4" x | established g trees: Fire Ceo. 970, Donald stances from d: T 46-47 ld corner in or Gogebic Co. bed bearing dence found and/orn; 10" Y. Bi 4" post - S | d by Austin But r 8" S A dar 14" N Lappala, RLS, the Cedar B.T N; R 44-45 W; Forest Servic ounty, from wh trres: 6" Y. nethod applied in restoring rch - S 06° W 40° E - 3 fee | rt in 1847. 40° E 24 1 44° W 3 1 restored co . He set a 2 S-36,S-31,S- e Liber for ich he estab Birch - N 88 orreestable leng com - 42.3'. t was added. | inks inks rner posi ½" iron p 1,S-6; R. land corr lished th 50 W - 31. | tion at lipe with L.S. 125 lers in R | 85; 1970. Register of ving new |
| Found the monum | | ring trees as | described ab | oove. | | |
| Act 74 research | on file. | | j | PEER Reclard L. J. | | 5/12/97 MILLINE |
| C. Description of monuments From the monumer reference object 9" Yellow Birch 7" Cedar 12"Yellow Birch 4"x4" wood Post 7" Yellow Birch 6' Rail & sign (All measurements Signed by John 6 | ent, I establets: N 880 N 070 S 060 S 400 N 730 N 330 At taken to | W 31.94' W 17.42' W 42.25' E 3 ft. E 13.86' E 2.7 ft. a nail in side | sting and ne | sition of the cornew bearing | Trees and John Sun | AND STANDS |
| Surveyor's Michigan License | ∍ No2? | 3509 | | | | |
| • | 771 - | A No. 7-25 | | | | |