## REMONUMENTATION

NOV 1 2 1997

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office Cogobic County


Received for record the
day of August
A. D. 1997 at 11:00 s'clock
m., and recorded in
and the same of th
Tage 186
Remona Collina Do atto
Ramona Polism Deputy Register of Devide

Fo	r corners in	and a physical of the graph of the first of	,	_ 18 day of August	
_(	Gogebić (County)	Located In:	Corner Code ##	A. D. 1997 at 1/:00 e'clock	
1.	Public Land Survey	T <u>47N</u> R <u>44W</u> T <u> </u>	D-3	A m., and recorded in  Cher 6 of Corners  page 186	
2.	Property Controlling in Section	T R S T R S T R		Register of Devide	
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
	Lot No, Private Claims	Recorded Plat		A 8 C D E F G H I J K L	

cor. 5 & 8; T.47 N., R.44 W.

<u>Drahn</u>, in a field survey on . August\_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1848. Original B.T.s --- Sug N.35 W. 22 links (14.52') --- Hemlock 12" S.30 E. 32 links (21.12') Original B.T.s --- Sugar 14"

Corner restored on 8/3/83 by R. Drahn (21564) from the remains of the two original B.T.s, and distances to recovered corners east and west. He set a 2" X 30" aluminum pipe with a 3½" stamped alum. cap and the following new B.T.s: --- 17" (19") Sugar Maple N.19 E. (N.18 E.) 33.24' (33.27')--- 8" (9") Yellow Birch S.31 E. (S.33 E.) 35.02 (35.00')--- 19" (21") Hemlock S.66 W. (S.64 W.) 54.13' (54.36').

Corner recorded in Gogebic County in Liber 2, Page 519 on 1/26/84. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Research form on file with Gogebic County records.

Recovered the corner as described and the bearing objects as indicated in parentheses above. The original Sugar B.T. is now a large, badly decayed stump; and the Hemlock is now a large stump hole.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described monument I established the following new B.T.s:

Steel sign rail

North

5"

Sugar Maple

N.53 W. 18.88'

PEER GROUP APPROVED

RICHARD L. DRAHN LAND SURVEYOR No. 21564

OF MICH

LAND

August 8, 1997 Date \_\_

21564 Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAH., 1983