REMONITION

NOV 1 2 1937

Register's Office LAND CORNER RECORDATION CERTIFICATE Gogetic County SS. Filing Requirement of Act 74, Mich. P.A. 1970 Received for record the 18 day of SEPTEMBER For corners in Corner Code # Located In: Gogebic A. D. 19 17 at 10:45 o'clock __m., and recorded in t46nr 1. Public Land Survey OF CORNERS me page 203 Pamona Collins Deputy Register of Deeds 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number _, Recorded Plat_ 4. Lot No. 5. Private Claims I, <u>John P. Goss</u>, in a field survey on <u>Aug. 18</u>, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. 1/4 cor. comm. to sec's. 5 & 32 A. Description of original monument and accessories and/or subsequent restoration: Original corner established by Austin Burt in 1847.
Original bearing trees: Spruce N 37° W 41 1
White Pine N 76° E 37 1 41 links On October 5, 1970, Donald D. Lappala, RIS, restored corner position at record bearing and distance from the two original bearing trees: A large decayed spruce stump and a 30" decayed white pine stump with scribed visible. He set a 2½" iron pipe with 3" cap and new B.T. - 12" Black Spruce N 33° W- 23.0'; 9" Cherry-N 13° E - 38.2'; 4" White Spruce-S 26° W- 10.3'. Corner recorded in USFS Liber Z-7, on August 10, 1972. 37 links B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
In 1992 a 4" by 4" wood post North and a 3" Maple- N 590 W- 22.96" was added. Recovered the monument as described above and 2 bearing trees and 1 stump. Also recovered a large spruce stump from original bearing trees; I updated the corner monument and accessories as noted below to state and county specification. Act 74 research on file. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner From the 22" iron pipe with 3" bronze cap which reads: T. 46-47 N., R.44 W.; 1/4; S-5, S-32; R.L.S. 12585; 1970, from which I established the existing and E OF MICHIGAN new bearing trees and reference objects: N 33° W N 13° E S 26° W 12" Black Spruce(stump) JOHN F GOSS 38.231 12" Cherry 10.35 9" White Spruce AND N 590 W 22.901 4" Maple SURVEYOR 1.15' (to face)
1.57' (to face) N 300 W 4"x4" wood post & sign Due S. 6 Rail and sign MED LAND (measurement to nail in side of tree) 1997 Date August 18, John P Doos Signed by _ 23509 Surveyor's Michigan License No.

Fed. No. Z-7