

SURVEY & REMONUMENTATION
APR 07 1995
COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Gogebic (County) Located In: Corner Code #
 1. Public Land Survey T 47N R 45W B-7
 Section 18 T _____ R _____
 T _____ R _____
 T _____ R _____
 2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
 3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

Register's Office }
 Gogebic County } ss.
 Received for record the
21st day of OCTOBER
 A. D. 1994 at 11:15 o'clock
A m., and recorded in
 Liber 5 of CORNERS
 on page 148
Ramona Collins, Deputy
 Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____
1/4 Cor. Comm. to Sec's. 18 and 19

I, John P. Goss, in a field survey on September 2, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7	●											
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 Original survey by William Burt in 1848. Set Cedar Post
 Original Bearing trees.
 16" Hemlock-N10°E-22links; 8" Fir-S25°W-27 links.
 Concrete monument set for Plat of Plymouth in 1958.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 Set P.K. nail in road at location of 1/4 corner by using plat monuments and lot corners.
 Act 74 research on file with the County Register of Deeds Office

PEER GROUP **Approved**
Richard P. Ordan 10/12/94




C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 A P.K. nail marks the corner position from which I established the following bearings objects:

I set reference monuments #1 and #2 consisting of 2 1/2" diameter x 30" long aluminum pipe with 3/4" diameter cap stamed to note the corner position as follows:

- R.M. #1 S41°W - 32.65' - steel sign post-1.15'
- R.M. #2 S59°E - 37.55' - steel sign post-1.10'
- D.H. nail in P.Pole S63°E - 37.86'
- D.H. nail in T.Pole N28°W - 30.45'
- D.H. nail in T. Pole N46°E - 44.63'

Signed by John P Goss Date 9-16-94
 Surveyor's Michigan License No. P.S. 23509



No Scale

