SUFFVEY & REMONUMENTATION

1993

LAND CORNER RECORDATION CERTIFICATE

Register'	s Office	
Register' Gogebic	County	} 33.

For corners COMMISSION		SION Filing Requ	irement of Act 74, Mich. P.	A. 1970 Received for record the
	Gogebic (County)	Located In:	Corner Code ##	A. B. 19 73 at 2:25 o'clock Pm., and recorded in
1. Pi	ublic Land Survey Se	ection 8 T 47N_ R .45W T R T R T R		on page 299 Betty Same Deputy
	roperty Controlling Section	S T R S T R	· · · · · · · · · · · · · · · · · · ·	Register of Geeds
	iscellaneous operty in Sec.	S T R S T R		Register of Deeds Stamp & File Number
	ot No , ivate Claims	Recorded Plat		ABCDEFGHIJKL
J. FI		r corner common to S-7 &	S-8, T47N, R45W	2 6 5 4 4 3 2 1 1

John R. Garske , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12 13

A. Description of original monument and accessories and/or subsequent restoration:

Survey by William Burt, 1848. Set sugar post from which a 7" fir bears S40°E, 15 links and a 10" fir bears N50°W, 16 links. No original evidence found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a "T" iron with 1" cap. Set by G. Wilson, R.L.S. in plat work for Indianhead Mountain in early 1970's. The corner was used in the subdivision of Section 8 and has been used and accepted by county agencies, local residents and in various surveys.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced found "T" iron with 2 1/2" x 30" aluminum county monument - with 3" aluminum cap stamped: County Remonumentation; T47N, R45W; 1/4 cor.; S-7; S-8; 1993; R.L.S. 28410. Established the following bearing trees and reference objects:

10" sugar - S77°W - 13.69 feet 3" Ironwood - N30°E - 6.10 feet 8" Ironwood - S22°E - 12.64 feet Steel sign post - due east - 2.00 feet

Surveyor's Michigan License No. .

28410

JOHN R.

garske

LAND SURVEYOR No.

FORM APPROVED BY MICHIGAN STATE BOARD BEY AND SURVEYORS, JAN. 28, 1971

REVISED JAN., 1983