## SUAVEY & REMONUMENTATION

AUG 0 8 1997

MARCOLLINGS

	001UM				
For comercia		D CORNER RECORDATING Requirement of Act 7			Office \ ss.
For corners in				•	ceived for record the
Gogebic (County)	Located In:	Corner Code #	İ	13 74	day of Mar
	-1 7NY-	) Eter m 4		A. D. 19.7	7 at 2:05 e'clock
1. Public Land Survey	T <u>47N</u> R T R	<u>45</u> W <u>E-6</u>		<u> </u>	m., and recorded in
	TR			Liber 6	Of CORNERS
2. Property Controlling	TR S T R			A 1-0	115
in Section	S TR			Damono	Collin Depat
Miscellaneous     Property in Sec.	S TR			•	Register of Deeds
r roperty in dec.	S IR_			Register of Deeds	Stamp & File Number
4. Lot No, Rec	orded Plat				
5. Private Claims			<del></del>	ABCDEF	GHIJKLM
1/4 cor. comm.	to sec's. 16	& 17		2 6 - 5 4	3-1-2-1-1-
I John D. Chaa	in a fold surround	Annil 20an 07		3	
I, John P. Goss , in a field survey on April 3019 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in				4 7 8 9	)101212
conformance with regulations at United States Department of the	e Interior, Bureau of Land M	fanagement or by a decree of a (	Court of Law and Jor	5 17 16	
that the corner points mentione Board of Land Surveyors or I	ed in lines 3, 4 and 5 above :	were in conformance with the ru	ites of the Michigan	7	151413
recovered, found as expressed l	below:	Com, established, re-establis	neu, monumentea,	8 19 20 21	22 23 24
NOTE: Not more than 2 co	mers, all in the same towr	n and range, may be recorded	d	9	
on this certificate.	•	•		10 30 29 26	3272625
				11	
				12 31 32 33	34 35 36
John R. Garske and 1/2 the di	er established ing trees: Tam Tan set a 5/8 in stance betwee	es and/or subsequent restor i by William Bur marack 8" N 400 marack 8" S 600 nch rebar by sir en the N.W. corn rded said corner	rt in 1848. W 6 lin E 25 lin igle propor	ks. tionate meas	urement, on lin
Power Pole N	gento Conuch.	. He established .05' Power E	the followed the f	ws reference	4 of Land objects:
B. Description of corner ev	idence found and/or me	thod applied in restoring or i	reestablishing corne	r:	
No original ev I found two (2 corner to Stat	) or lour K*	due to corner Garske witnesse specification.	falls in co	enterline of ch I reestabl	road. lished the
Act 74 research	h on file.				
	·	Ribard P. CCUNTX	DELL 5/12/	lar	
C. Description of monument	t for corner and accessor	ries established to perpetual	te locating the position	on of the corner	
at the corner aluminum cap so 1/4; S-16, S-16 I established	location I se tamped to read 7, 1997; P.S.	t a 5/8 inch by d: County Remon 23509. Buriëd reference obje	20 inch re umentation, 6 inches be	bar with a 3	45 W.
P.Pole #41	S 400 W 39.0	081		تم	Ellen mining
P.Pole #453 1	$N 23^{\circ} E 76.$	<i>5</i> 7 <b>'</b>		Ž.	JOHN P. X.
Aluminum monume	ment cosisting ent with a 31	g of 2½" by 30" " aluminum cap			GOSS (*)
stamped to ind:	icated corner	position.			SURVEYOR No.
S 400 E - 48.5 Signed by John O	7': with $6^{+}$ r:	ail & Sign @ 1.	42' Date <u>April</u>		23509
Surveyor's Michigan License		····	<u></u>		WALL TAND
	Fed.	No. L-9			