BURVEY & REMONUMENTATION

AUG 0 8 1997 Register's Office ss. LAND CORNER RECORDATION CERTIFICATE
COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 Cogebic County Received for record the For corners in 11 day of JUNE Gogebic Corner Code # Located In: A. D. 1947 at 10:35 o'clock (County) m., and recorded in T47NR44W 1. Public Land Survey O CORNERS 747NR45W 143 R 2. Property Controlling R Register of De in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims 1/4 cor. comm. to sec's. 1 & 6 , John P. Goss , in a field survey on June 2, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original corner established by Austin Burt on Sept. 1, 1847. Set Hemlock post. Original bearing trees: Hemlock 14" S 73° W 21 links S 73° W N 49° E Original bearing trees: Hemlock 14" Sugar 7" N 49° E 23 links
On August 21, 1986, Richard Drahn, RLS, reestablish the corner position on line and proportionate distances from Section corners: 39 chain North and 80 chain South. He set a 2" I.D. iron pipe with 3" brass cap, stamped to indicated corner position. He record said corner in Liber 3 page 24 of Land Corners for Gogebic County. He established the following reference objects. 7" S. Maple - N 06° E 40.38; 8" Cedar - N 88° E- 11.83; 7" S. Maple - S 11° E - 46.17; 6'Metal B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Sign Post - N 890 E - 1.8 No original evedence could be found. Found Drahn, 2" iron pipe with brass cap. It checked with Drahn witnesses. I updated the accessories as noted below to state and county specification. Act 74 research on file. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the 2" I.D. iron pipe with 3" brass cap marked T.47 N., R.44-45 W.; 1/4; S-1, S-6; 1986; R.L.S. 21564. I established the existing and new bearing trees P. COLORINA and reference objects. E OF MICHIGAN N 06° E 9" Sugar Maple 40.381 N 880 E 8" Cedar (Stub) 10" Sugar Maple 11.83 JOHN P. S 110 W 46.171 GOSS N 450 W 8" Basswood 16.91 и 890 1.8' (to face of post)
2.0' (to face of rail) 6' Metal sign post \$ 60° W 6' Rail & Sign No.

Fed. No. C-25

(measurement to nail in side of tree)

23509

John P Hoss

Surveyor's Michigan License No.

Date <u>June 3, 1997</u>

23509