	LAND CORN	IER RECORDATION CERT	IFICATE Gogebic County (58.
corners in	Filing Requirement of Act 74, Mich. P.A. 1970		ACCOUNT TO I SHOULD WIND
Gogebic (County)	Located In:	Corner Code ##	12 22 day of APRIL A D 1995 at 1:15 o'clock
Public Land Survey	S-36 T 47N R 47W T R	M-11	Liber 5 of Conner  Page 236
Property Controlling in Section	S T R S T R S T R	<u>A-11</u>	Register of Deeds Stamp & File Number
Property in Sec.	S T R		negister of Deeds Stamp & The Name
	Recorded Plat		A B C D E F G H I J K L M
One-quarter corner cor	mmon to Sections 25 and 36, T4	7N, R47W and	

10

Register's Office

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

, in a field survey on ...

On September 6, 1847, William Austin Burt set a sugar post from which a 8" tamarack bears N80°E, 22 links and a 8" spruce -N67°W, 17 links.

March 23

- U.S.D.A. Form 874-9 dated 1/3/36. Found square tree in good condition with a metal tag on east side of a 6" cedar post. Field personnel state they did not believe this to be a genuine land office corner.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I established the corner position at the centerline intersection of town roads and verified the corner position with measurements to corners, north, south and west.

Record research on file with Register of Deeds.

For corners in

1. Public Land Survey

**Property Controlling** 

in Section Miscellaneous Property in Sec.

Lot No.

expressed below:

Private Claims \_

John R. Garske

Sections 30 and 31, T47N, R46W.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3 1/4" brass cap stamped: T47N, R47W, R46W; S-25; S-30; S-36; S-31; 1995; RLS 28410, from which I established the following bearing trees and/or reference objects: 10" apple - N22°E, 85.81 feet; P. pole - S34°E, 41.66 feet; clump of 3 - 10" R. maple - N44°W, 100.95 feet; a reference monument consisting of a 2 1/2" diameter x 30" aluminum pipe with a 3 1/4" diameter aluminum cap stamped: County Remonumentation; T47N, R47W, R46W; S-25; S-36; S-30; S-31; 1995; R.M.; RLS 28410; N53°E, 61.87 feet; a 6 foot steel rail with sign 1.22 feet away.

Signed by Surveyor's Migh gan License No.

GARSKE LAND SURVEYOR

28410

REVISED MAY 14, 1975 REVISED JAN., 1983

Fed. No. V-25