	•	4 - K		•
		I AND CO	RNER RECORDATION CER	TIFICATE Register's Other
				BA 4070 Gogebic tounty SS.
Fo	r corners in	riing neq	uirement of Act 74, Mich. I	Received for record the
	CLi-	Located In:	Corner Code ##	19 Threa for record the
	Gogebic —	Eucated III.	Comer Code 44	1
				A. D. 1995 at 10:10 o'clack
1.	Public Land Survey	S-31 T 48N. R 46V		M., and records ! :-
		S-6 (<u>47N R 46V</u>		Liber 5 of Corners
		TR		00 page 297
_	Danmarky Controlling	T R		Ramona Collins Deporter
2.	Property Controlling in Section	S T R S T R		
3.	=	S T R		Register of Doods
3.	Property in Sec.	S T R		Register of Deeds Stamp & File Number
	rioperty in Sec.	3 1 n		,
4.	Lot No.	. Recorded Plat		
	One-quarter corner to	Section 31 & 6, T48-47N, R4	6W	2 - 6 5 3 2 1 -
	One quarter termer to			3
				4 7 8 9 10 11 12
I, John R. Garske in a field survey on October 4 19 95 . 5				
		· ·	P.A. of 1970, the corner points men	011017161161141313
			s and rules therefore as required	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in times 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a				
				91 1 1 1 1 1 1 1 1 1 1
	•	, re-established, monumented,	re-monumented, recovered, fou	and as
•	oressed below:			
NC			n and range, may be recorded	
	on this certificat	ie.		12 31 32 33 34 36
Α.	Description of origina	al monument and accessories	and/or subsequent restoration	n:
• •	,			
	 Original corner v N36°E - 20 links 	-	Burt, D.S., on September 9, 18	847. Original bearing trees: Hemlock 12" -
	- Plat of Caribou	Village recorded 1981 shows co	oncrete monument at one-quarte	r corner by Duane Peterson, RLS.
		_		Q
В.	Description of corner	evidence found and/or method	od applied in restoring or rees	tablishing corner:
	the one-quarter corne	er position. In addition, ties to r The corner position checks with	ecorded corners east and west w	bou. Measurements to found plat corners confirm /ere also used to confirm the monument as the I-S 1/4 line as shown on the Plats of Alpine

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 4" diameter concrete monument with a 2 1/2" diameter x 30" long aluminum pipe with a stamped 3 1/4" diameter aluminum cap from which I established the following bearing trees and/or reference objects:

4" S. maple - N70"W - 8.24 feet 6" Ironwood - N28"E - 17.96 feet 8" S. maple - S71"E - 25.35 feet 6' steel sign rail with sign - S14"W - 1.92 feet

10/10/95 REPRESENTATIVE COUNTY

GARSKÉ LAND SURVEYOR

No. 28410

JOHN R.

Surveyor's Mighigan License No. 28410

(Record research on file.)