FEB 1 8 1994

COMMISSION

Gogebic

2. Property Controlling

Property in Sec.

in Section

3 Miscellaneous

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code ##

Register's Gogebic	Office	
Gogebic	County	788

Beceived	for	record	the
30 29	of.	DECKM	34
L. D. 19 <u>43</u> at			
<u>Р</u> т.,	and	recorde	l is
Uber 4			
m page 342			
		n	

1. Public Land Survey Section 3 T 47N R 46W I-1T _____ R ____ Register Register of Deeds Stamp & File Number

__ , Recorded Plat __ 5. Private Claims _ Section corner common to S-2 & S-3, T47N, R46W and S-34 & S-35, T48N, R46W. 19 93 December 27 John R. Garske , in a field survey on _

Located In:

__ T ____ R _

S T R _

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

7

Survey by William A. Burt on September 9, 1847. Set sugar post from which a 20" sugar bears -

10

11

12

Description of original monument and accessories and/or subsequent restoration:

N62°E - 34 links and an 8" hemlock bears N57°W - 29 links and a 10" sugar bears S65°W - 19 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence found. Found a 6" nail at the intersection of a two-track road to north and an old North-South fence line to the south and at the center line of Stone Road. This corner position has been used in several surveys and is generally accepted as the most probable location of the original section comer by both local surveyors and area residents. Due to the history of the cornr location and its general use and acceptance, I am accepting it as marking the true section comer location. OF HICA

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner 28410

Replaced the nail with a 3/4" x 30" iron rod with a stamped 3 1/2" diameter aluminum cap from which I established the following bearing trees and reference objects:

18" apple - S39°E - 40.36 feet 5" basswood - N19°W - 34.40 feet

Reference monument - N25'E - 34.89 feet. Set 2 1/2" x 30" aluminum County Monument with a 3 1/2" stamped aluminum cap - steel sign post - 1.33 feet.

Reference monument - S57°W - 47.78 feet. Set 2 1/2" x 30" aluminum County Monument with a 3 1/2" stamped cap - steel sign post - 1.96 feet.

____ Date __ Signed by Surveyor's Michigan License No. 🗕

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

JOHN R. GARSK2 LAND SURVEYOR