## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office ss.

For corners in	Filing Requir	ement of Act 74, MICII. P.A	1279 day of MAY
Gogebic	Located In:	Corner Code =##	A. D. 1995 at 11:20 o'clock
Public Land Survey	T <u>47N R 46W</u> T R T R	K-2	A
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R S T R S T R S T R		Register of Deeds Stamp & File Number
5. Private Claims	Recorded Plat  . to sec's. 1 & 2		2 6 5 3 2 0
do hereby certify that under rein lines 1 and 2 above were current manual of survey inst Management or by a decree of above were in conformance will Court of Law; established, expressed below:	in a field survey on Aprequirements of P.A. 74, Michigan P.A. in conformance with regulations at ructions of the United States Departs a Court of Law and/or that the cornyith the rules of the Michigan Board re-established, monumented, re-	to 1970, the corner points mention of rules therefore as required in rement of the Interior, Bureau of Lier points mentioned in lines 3, 4 and 1 Land Surveyors or by a Decree monumented, recovered, lound	oned 6 18 17 16 15 14 13 14 13 14 15 16 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16
NOTE: Not more than 4 on this certificate	corners, all in the same town a e.	ind range, may be recorded	11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:
Original Survey by Austin Burt, D.S. on June 10, 1851. Set post.
Original Bearing Trees: Sugar 12"-S82°W-25 links; Y.Birch 12- N 76°E- 15 links.

John R. Garske in 1989 found a 12" iron pipe located at corner, approximately 8" below surface of gravel roadway. He recorded it in Liber 3 page 284 of Land Corner for Gogebic County: 6" Aspen- N 62°E-66.24'; 6" Maple clump- N 68° W- 32.76'; Power Pole- S 37° W- 39.06'; all corners have D.H. Nail/ cap.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the iron pipe marking the corner position buried about 8 inches and it checked with the three (3) bearing objects in John R. Garske certification. I updated the corner monument and accessories as noted below to state and county specification.

Act 74 reseach on file with the County Register of Deeds Office.

PEER GROUP APPROVED

Richard K. Wracu 5/11/95

COUNTY HETHESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 5/8" x 24" rebar next to the iron pipe with a 3½" aluminum cap 6"
below the road surface stamped: County Remonumentation; S-1; S-2; T.47 N.;
R.46 W.; 1/4; 1995; P.S. 23509. I established the following bearing trees
and reference objects.

D.H. Nail & Cap in 8" Aspen

D.H. Nail & Cap in 9" Maple clump

D.H. Nail & cap in Power Pole

D.H. Nail & cap in Power Pole

S 37° W 39.06'

reference monument consisting of a 2½" x 30" aluminum monument with a 3½" aluminum cap stamped to indicate corner position: S 54° E- 47.41 with a 6' Steel Rail and sign- 1.00'.

Signed by John P Hossissian Surveyor's Michigan License No.

Date \_\_\_\_April 23, 1995

P.S. 23509

JOHN P. GOSS LAND

SURVEYOR

Nn.

23509