Register's Office ss. LAND CORNER RECORDATION CERTIFICATE Gogebic County [Filing Requirement of Act 74, Mich. P.A. 1970 Received for record the For corners in 19th day of October Gogebic Located In: Corner Code ## A. D. 19 95 at 10:10 o'clock A m., and recorded in 1. Public Land Survey T 47N R 46W Of CORNECS Liber 5 R R on page 299 R Kamona Collins Diputy **Property Controlling** T R Register of Deeds in Section Т Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat _ 5. Private Claims One-quarter corner common to Sections 1 and 12, T47N, R46W. 95 October 11 John R. Garske in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Description of original monument and accessories and/or subsequent restoration:

Survey by Austin Burt on June 10, 1851. Set wood post from which a 10" hemlock bears S09°E - 42 links and an 8" fir bears N24°W - 38 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence found due to logging activity. Found a 2 1/4" O.D. iron pipe - N05°E, 10.86 feet from the corner location. Probably set by Gunner Lorenson, Forester in Work around the Blackjack Ski area. I did not accept. Corner set by single proportionate method on line and one-half the distance between opposing section corners in accordance with the original government notes. Old fence lines run east and south from our corner position.

(Record research on file.)

on this certificate.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 2 1/4" x 30" aluminum pipe with a stamped 3 1/4" aluminum cap from which I established the following bearing trees and reference objects:

4" B. ash - N37°W - 34.75 feet 12" tamarack - S50°W - 16.91 feet 10" spruce - S57°E - 47.90 feet Steel sign post - due south - 0.90 feet

OF HICH JOHN R. GARSKE LAND SHRVEYOR No. 28410

Signed by

Surveyor's Michigan License No.

FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983