	Register	's Office	
:	Register Gogebic	County	} S <b>S</b> .

		LAND COR	NER RECORDATION CERTIFIC	CATE Gogebic County ss.			
			irement of Act 74, Mich. P.A.	1970 Beceived for record the			
For	corners in			30 TH day of DECAMBER			
	Gogebic	Located In:	Corner Code =##	A. D. 1993 at 12:25 o'clock			
,	(County)						
1	Public Land Survey	т <u>47N</u> R <u>47</u> W	I G-1	Pm., and recorded in			
١.	Fublic Land Survey	T R	1	liber 4 of CORNERS			
		T R	T T	on page 329			
		T R		Betty Sagrie Denit.			
2.	Property Controlling	S T R		(legister) of Alecds			
	in Section	S T R		g			
3.	Miscellaneous	S R		Register of Deeds Stamp & File Number			
	Property in Sec.	S R					
		D da d. Dlad					
				A B C D E F G H I J K L M			
5.	Private Claims		S-33 & S-34, T48N, R47W.	2 6 5 4 3 2 - 1 -			
	Section co.	mer 3 & 4, 14/N, R4/W,	3-33 & 3-34, 146M, K47W.	3			
			December 15 93	4 7 8 9 10 11 12 12			
ı J	John R. Garske	. in a field survey on	, 19	_ , 5			
dot	hereby certify that under r	requirements of P.A. 74, Michigan P	.A. of 1970, the corner points mentions				
in li	ines 1 and 2 above were	in conformance with regulations	and rules therefore as required in the partment of the Interior, Bureau of Lar	ne 7			
Mar	nanement or by a decree o	of a Court of Law and/or that the co	rner points mentioned in lines 3, 4 and	15 8 19 20 21 22 23 24			
aho	ve were in conformance:	with the rules of the Michigan Boar	rd of Land Surveyors or by a Decree of	fa			
		, re-established, monumented, r	e-monumented, recovered, found	as 10 30 29 28 27 26 25			
	oressed below:	servers all in the come town	and range may be recorded	11			
NO		corners, all in the same town	and range, may be recorded	12 31 32 33 34 35 36			
	on this certificat	. <del></del>		13			
Α.	Description of origina	al monument and accessories	and/or subsequent restoration:				
	A. Description of original monantain and acceptance than a control of						
Sugar post set by William Austin Burt, August 1848.							
Elm 14" - N70°E - 25 links							
	Ein	n 12" - N7°W - 11 links					
				liabias assault			
В.	Description of corner	r evidence found and/or metho	od applied in restoring or reestable	lishing corner:			
	No origina	l evidence found. Found a	P.K. nail at the corner loction	at the center line intersection			
	of Vanderi	lagen and North Star Koads	s. This corner position has be	een used and accepted as the			
	section cor	ner in several surveys of re	cord, by area residents and the	ne County Road Commission.			
	•			ASSESSED FOR COMMENTER OF THE COMMENT OF THE COMMEN			
				613			
				JOHN R.			
				#* GAREKE \			
				LAND O			
				SURVEYOR "			
			•	Mo. 28410			
			•	Control of the second of the s			
C.	Description of monur	ment for corner and accessorie	es established to perpetuate loca	aling the position of the corned IAND			

reference objects: Light pole - N21°E - 84.24 feet

Telephone pole - S50°E - 47.88 feet Power pole - S34°W - 62.30 feet Power pole - N43°W - 49.94 feet

Set two reference monuments being 2 1/2 x 30" aluminum Bernsten monuments with 3 1/2" caps stamped: County Remonumentation, 1993, S-3, S-4, T47N, R47W, S-33, S-34, T48N, R47W RLS 28410. - N45°E - 60.00 feet and steel rail 2.00 feet and a reference monument - Set at S57°W

Replaced nail with an 8" cotton gin spike and established the following bearing trees and/or

- 61.00 feet and steel rail 1.99 feet, Date \_ Signed by Surveyor's Michigan License No. 28410