LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ATE 970		1972 . 19 <u>9</u>	eceiv	ed l lay d at	or 1 of <u>A</u> 1:20		lock	
	Liber on p		90		ol S na	ORN	ese Out	y
Regis	ster of E	eeds	Star	mp 8	File	Num_	ber	
	A B	с <u>о</u>	_€_	f c	<u>н</u>	† į	K i	, ,

___, Recorded Plat _____

4. Lot No.

expressed below:

5. Private Claims

May 10

94

1, John R. Garske, in a field survey on 19

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original survey by William Ives in 1848. Set a post. Original Bearing Trees:

14" Y. birch - N22°W - 8 links; 10" Y. birch - S60'E - 9 links

Original Plat of Ironwood - 1885 and Case and Longyear's Addition - 1887. Set 1" iron stake.

1976 survey by Ewart C. Muller, RLS 15408. Found 1" iron stake as called out in above plat and recorded in Liber 1 of Land Corners, page 191. Accessories: P.Pole - S14°W - 76.56 feet; P. Pole - N51°W - 62.8 feet; P. Pole - N06°W - 59.16 feet.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the 1" iron stake marking the corner position and checked with Muller's witnesses in his certificate. I updated the corner monument and accessories as noted below to state and county specifications. Corner is approximately 1 foot off back of sidewalk.

Act 74 research on file with County Register of Deeds Office.

PEER GROUP Approved

Richard L. Wealn 8/12/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap stamped: 1/4, S-21, S-22, T47N, R47W, 1994, RLS 28410, over the 1 inch iron stake found. I established the following bearing trees and reference objects:

Power Pole - N04°W - 59.36 feet Power Pole - S11°W - 76.29

N.W. Cor. House No. 416 - S75%E - 19.43 feet

S.W. Cor. Garage @ House No. 420 - N23°E - 63.81 feet

JOHN R. GARSKE LAND SURVEYOR

No.

28410

GRM APPROVED BY MICHIGAN STATE BOAR

WAND SHEVE TORE SAH. 28, 15

REVISED JAN., 1983

Surveyor's Michigan License No. 28

Signed by _