SURVEY & REMONUMENTATION

SFP 2 9 1994

ACKARAGE BARANA

LAND CORNER RECORDATION CERTIFICATE

Register's Office Gogebic County

COMMISSION CONTRACTOR		Filing Requirement of Act 74, Mich. P.A. 1970			16 m day of Sapr			
For	corners in Gogebic	Located In:	Corner Code =##			(2) (94_at_		
	(County)	Located III.	Comer Code -F4			m, an		
1.	Public Land Survey S-2	T R	I-1		Liber	5	ol <u>Corn</u>	vers
2.		T R T R T R			Park I I I I I	Keg	ister of	Deeds
3.	Miscellaneous S			Registe	r of Deeds	Stamp & f	File Numb	er
	Lot No, Recorded				A B C D	E F G	ніј	KLN
5.	Private Claims Section corner common			2	65-	+++	32-	
do l in li cur Mai abo Cou	John R. Garske , in a finereby certify that under requirement ines 1 and 2 above were in conformate manual of survey instructions of the manual of survey instructions of the manual of survey instructions of the manual of survey in the restablished of the survey of the manual of the	ats of P.A. 74, Michigan P.A. of mance with regulations and of the United States Depart of Law and/or that the cornel les of the Michigan Board of	of 1970, the corner points ment it rules therefore as required i ment of the Interior, Bureau of r points mentioned in lines 3, 4 f Land Surveyors or by a Decre	ioned 6 in the Land 7 and 5 8 see of a 9 nd as	18 -17-	9 16 21 23 23	15 14 22 23 - 23 - 27 - 26 -	13-
NO	TE: Not more than 4 corners, on this certificate.	all in the same town an	d range, may be recorded	11 12 13	3132-	33-	3435-	36-

Description of original monument and accessories and/or subsequent restoration:

Original survey by William A. Burt, D.S., in 1847. Set sugar post. Original bearing trees: Hemlock 18" - N22°E, 33 links; Sugar 8" - N50°W, 55 links.

The corner position was found by John P. Goss, RLS 23509, in April 1978 marked by a brass cap set in concrete pavement by the U.S. Department of Agriculture Farm Security Administration in 1938. He recorded the corners in liber 1 of land corners P. 377. He set a P.K. nail in a blacktop road at the corner location. Accessories: P. pole - S63°W, 48.90 feet; T. pole - N72°W, 80.39 feet; L. pole - N50°E, 51.70 feet; N. pine 12" - S44°E, 57.97 feet.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a P.K. nail in blacktop pavement marking the corner position which checks with Goss' witnesses in his certificate. I updated the corner as noted below to bring it up to county and state specifications.

Act 74 research on file with County Register of Deeds Office.

PEER GROUP Approved

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the found P.K. nail with a 2 1/2" brass cap with a 2" stem set in anchoring cement 1/2" below pavement. Cap is stamped S-34, S-35, S-2, S-3, T48N, T47N, R47N, 1994, RLS 28410. I established the following reference objects: Reference monument consisting of a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap stamped to indicate the corner position as follows:

R.M. - S54°W, 46.10 feet - with steel sign post 1.64 feet away; P. pole - N67°W, 83.85 feet; P. pole - S25°E, 96.15 feet; existing P. pole - N50°E, 51.70 feet. JOHN R

Signed by

Surveyor's Michigan License No. ...

Gerske

Garske LAND

SURVEYOR

28410 OF LAND SU

FED No. A-17