

on this certificate.

Surveyor's Mighigan License No. 28410

SEP 2 9 1994

COMMISSION

Register's Office

	LAND CORNE	R RECORDATION CERTIF	ICATE HORESIC (HORE)
For corners in	Filing Require	ment of Act 74, Mich. P.A	1. 1970 Received for record the
Gogebic	Located In:	Corner Code ≠≠	A. D. 1994 at 4:10 o'clock
(County)			P m., and recorded in
1. Public Land Survey S-35	T 47N R 47W	ı.	Liber 5 of CORNERS
	T R		on page /39
	T R T R		Kamona Collins, Deputy
			Register of Beeds
in Section S	i T R		
<ol><li>Miscellaneous S</li></ol>	TR		Register of Deeds Stamp & File Number
Property in Sec. S	TR		
4. Lot No, Reco			ABCDEFGHIJKL
5. Private Claims			2 6 5 4 3 2
One-quarter corner o	common to Sections 3	35 & 2	3
			4 7 8 8 1 9 10 11 12
John R. Garske , in	a field survey onU	<u>ly</u> , 19 <u>94</u>	- · 5 <del>                                    </del>
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in tines 1 and 2 above were in conformance with regulations and rules therefore as required in the			hed 6 18 17 16 15 14 13 13 13 15 16 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16
current manual of survey instructions of the United States Department of the Interior, Bureau of Land			and 'l-l-l-l-l-l-l-l-l-l-l-l-l-l-l-l-l-l-l-
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			
Court of Law; established, re-esexpressed below:	tablished, monumented, re-m	onumented, recovered, found	as 9 10 30 29 28 27 26 25
NOTE: Not more than 4 corne	ers, all in the same town an	d range, may be recorded	11

Original survey by William A. Burt, D.S., in 1847. Sugar 4" is one-quarter corner. Original

bearing trees: Hemlock 26" - N64°W, 25 links.

The one-quarter corner position was set by John R. Garske, RLS 28410, in February 1983 using existing occupation lines and consists of a P.K. nail in the road intersection. The corner is recorded in liber 2 of land corners P. 300. Accessories: top of hydrant - N47°E, 57.82'; P. pole -N33°W, 44.62'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Description of original monument and accessories and/or subsequent restoration:

I found a P.K. nail marking the corner position which checks with witnesses on my previous recordation certificate and updated the corner as noted below to bring it up to county and state specifications.

Act 74 research on file with County Register of Deeds Office.

**Approved** PEER GROUP


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Using the existing P.K. nail at the one-quarter corner location, I established the following reference objects: Two reference monuments consisting of a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap stamped to indicate the corner position as follows: R.M. #1-S08°E, 34.20 feet - with steel sign post 1.94 feet away; R.M. #2-S64°W, 64.65 feet - with steel sign post 1.93 feet away; existing top of hydrant - N47°E, 57.82 feet; P. pole - N52°W, 44.65 feet.

SEE SKETCH ON BACK

JOHN R GARSKE LAND SURVEYOR

FED No. Z-19



SEP 2 9 1994

COMMISSION