LAND CORNER RECORDATION CERTIFICATE

Register'	's Office	
Register' Gogebic	County	53.

			_ ,
	Filing Requir	ement of Act 74, Mich. P.A. 197	
For corners in			19 day of AUGUST
Gogebic	Located In:	Corner Code ##	
(County)	Located III.	Comer code ===	A. D. 19 97 at 1:10 e'clock
•			P m., and recorded in
1. Public Land Survey	т <u>47N в 47W</u>	<u>L-1</u>	Liber 5 Of CORNERS
S-1	T R	**************************************	
	T R		on page 73
	T R		Kamona Callins, Deputy
2. Property Controlling S	S T R		Register of Beeds
• •	S T R		·
	S T R		egister of Deeds Stamp & File Number
	S T R	, , , , , , , , , , , , , , , , , , ,	egister of Deeds Stamp & File Number
Troporty in Odo.	-		
4 Lot No. Reco	orded Plat		
5 Private Claims			- ABCDEFGHIJKLI
5. I hade oldino		, <u> </u>	
		•	3
		May 5 94	
John R Garske	. a finial accuracy and		5 1 1 1 1 1
do harabu cartify that under require	ments of P A 74 Michigan P A	. of 1970, the corner points mentioned	
		nd rules therefore as required in the	6 -18 -17 -16 -15 -14 -13
		rtment of the Interior, Bureau of Land	7
		er points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
	_	of Land Surveyors or by a Decree of a	9
	stablished, monumented, re-	monumented, recovered, found as	10 30 30 30 37 36 35
expressed below:			30 23 20 21 20 25
	ers, all in the same town a	nd range, may be recorded	
on this certificate.			12 -31 -32 -33 -34 -35 -36
			13
		d/or subsequent restoration:	
Original survey	by William Austin Burt	t in 1847, set Ironwood post. O	riginal Bearing Trees:
Sugar 5" - N41	'F _ 29 links		
Dagat 2 - 1141	The state of the s		

Hemlock 6" - N46°W - 4 links

U.S.D.A. survey in 1938. Set a 5" x 42" concrete monument with stamped bronze cap. Chiseled "X"s in bedrock as witnesses.

Survey by John R. Garske, RLS 28410, in August of 1988. Found chiseled "X"s from U.S.D.A. survey. Reestablished corner position from these witnesses. Corner position matches GLO calls. Recorded in Liber 3 of Land Corners on page 253 by J. Garske.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" x 30" rebar with aluminum stamped cap with stone pile around it. Remonumented the corner position and updated the accessories as noted below to bring them up to state and county specifications. Corner accessories by Garske in good condition and are noted again below.

Act 74 research on file with County Register of Deeds Office.

PEER GROUP

Approved

Ridard L. Droll

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 5/8" rebar with a 3/4" x 30" long rebar with a 3" aluminum cap stamped: County Monumentation, T48N, R47W, T47N, 1/4, S-36, S-1, 1994, RLS 28410, from which I established the following accessories: (shallow bedrock in area did not allow a standard aluminum monument)

4" ash - S44°E - 52.76 feet

4" ash - N11°W - 7.76 feet

3" ash - Due East - 21.74 feet 6" Ironwood - S55"W - 10.14 féèt

EYORS, JAN. 28, 1971

JOHN R.

GARSKE LAND SURVEYOR No. 28410

Surveyor's Mich/gan License No.

Signed by .

28410

FED NO. A-23

REVISED MAY 14, 1975 REVISED JAN., 1983