MAR 0 2 2000					er's i					
SECTION For corners in		LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970		Received for record the						
Gogebic Li (County)	ocated In:	Corner Code #	~-		19_9	•	and r	ecord	'clock ed in	
1. Public Land Survey	T_48N.R_45W TR TR	M-10		en p	ye	194			enene Di	<b>'</b> F
2. Property Controlling in Section S. Miscellaneous S. Property in Sec. S.	T_48N R_44W TR TR TR	A-10	~~~~			K	egiste	r of	Godin He Nun	nber
4. Lot No, Recorded Pla			) 1	A B	с <u>в</u>	E F	G G	H 1	J K	L 
Quarter Corner 25 & 30; T.48 N.,	R.44-45 W.		<b>2</b> 3	6	<del>  </del> 5-	\dagger		3	-2- <del>-</del> -	- 1- -
I, <u>Richard L. Drahn</u> , in a field that under requirements of P.A. 74, Mi	chigan P.A. of 1970,	the corner points mentioned in	<b>4</b> 5		B- 	<u>}</u>	-	10	-1'1 <u>-</u> -	-12
lines 1 and 2 above were in conformant the current manual of survey instruction Bureau of Land Management or by a	ons of the United Sta decree of a Court of	otes Department of the interior, of Law and /or that the corner	6 7	18	17	16	5	5	-14	—1 <sup>3</sup> -
points mentioned in lines 3, 4 and 5 Michigan Board of Land Surveyors or re-established, monumented, recovered	or by a Decree of	a Court of Law; established,	9	19	20	2	1	22	-23- - -	<del>2</del> 4-
NOTE: Not more than 2 corners, all in the on this certificate.	e same town and range	, may be recorded	1 <b>1</b> 11	30-  31	32-			34	35	-25- -36-
A. Description of original monument a Original corner established b Yellow Birch 28" Hemlock 16"	y Austin Burt on 9/8 S.18° W. 30	or subsequent restoration: /1847. Original bearing trees: links (19.80') links (18.48')	13					1_1		

Corner restored by Donald D. Lappala, RLS 12585 on 8/29/72 from the remains of the two original B.T.s. The downed Y. Birch was still scribed. He set a 2" X 5' iron pipe monument with a 3" stamped brass cap and the following new B.T.s

N.52° E. 6" Sugar Maple 10.6 **7**" Sugar Maple \$.10°E. 11.9" Sugar Maple 6" S.87° W. 33.5' N.45° W. Metal sign post 6' 3.5

Corner recorded in Gogebic County USFS Liber, Page T-1, on 12/9/74.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I recovered the monument as described and the bearing trees as follows;

9" 10" Sugar Maple N.54°E. 10.53' (new nail) S.07° E. 11.71 Sugar Maple (new nail) 9" S.88 °W. Sugar Maple 33.54 (new nail) B.T. is now dead Steel sign rail 6' N.46° W. 3.52

A stump hole with fragments of Yellow Birch bark and wood remain from the original Birch B.T.. The original Hemlock is now a badly decayed Hemlock stump with portions of the B.T. overgrowth still visible.

Corner research on file with Gogebic County records.

С,	Description of monument for corner and accessories established to perpetuate locating the position of the corn	er: _
	New bearing tree referenced:	

Sugar Maple

S.84°W.

47.51

Date <u>July 19, 1999</u>

Surveyor's Michigan License No.

21564

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFE

1971 REVISED MAY 14,1975 REVISED JAN., 1983

OF MICH

RICHARD L. DRAHN LAND SURVEYOR No. 21564

REVISED OCT., 1995

USFS T-25