## SURVEY & REMONUMENTATION

AUG 0 8 1997 Register's Office ss. LAND CORNER RECORDATION CERTIFICATE Gogebic County COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 Received for record tine For corners in 11TH day of JUNE Gogebic Corner Code # Located In: A. D. 1997 at 10:35 o'clock (County) \_m., and recorded in 1. Public Land Survey T47NR\_ OF CORNERS T47NR 45W page 142 T48NR 45W 2. Property Controlling Register of Deeds in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number \_, Recorded Plat 5. Private Claims Sec. cor. comm. to. sec's. 1,6,31 & 36 John P. Goss, in a field survey on May 28, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original corner established by Austin Burt in 1847. Set post. Original bearing trees: Cedar 14" S 212 E 114 links.

Spruce 7" N 160 W 14 links. On August 22, 1968, Donald Lappala, RLS, restored corner at recorded bearing and distance from now 18" Cedar stump with scribing visible S 212° E - 62.7 feet.

Also recovered 14" Cedar stub witness with scribing visible S 06° W - 70.7 feet. Lappala recorded this corner in Forest Service Record book in Gogebic County Register of Deeds Office. He set a 2" iron pipe with 3" bronze table indicated corner location with the from witnesses. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

12" Cedar S 76° E - 82.0'; 12" Cedar S 35° E - 46.6'

4"x4"x7' Cedar Post S 38° E - 3.2'; 6" Cedar S 03° W - 71.2' 4"x4"x7' Cedar Post Cedar
Found 18"AStump @ S 21½° E - 62.7' and recovered 14" Cedar stub with scribing visible @ S 06° W - 70.7'. Also found Lappala 2" iron pipe with 3" bronze table and witnesses trees. The witnesses checked. I updated the accessories as noted below to state and county specification. Act 74 research on file. Example 2. Description of monument for corner and accessories established: T. 47-40 N., n., 44 From the 2. iron pipe with 3. bronze table stamped: T. 47-40 N., n., 44 From S-1, S-6, S-31, S-36; R.L.S. 12585, 1968. I established the following existing bearing trees and existing and new reference objects.

S 760 E 82.00'

JOHN P. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: JOHN P. GOSS s 030 W 10" Cedar 71.21' 4"x4"x7' Cedar Post & sign S 380 E LAND 3.2' (to face) 33° 6' Rail & sign  $\mathbf{E}$ 1.54'(to face)

> FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

Date May 28,

Fed. No. A-25

(measurement to nail in side of tree)

Signed by John P Joss

Surveyor's Michigan License No. 23509