LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's uffice

			ORDATION CERTIFIC		tounty St.
For corners in	CHE	ng Kedultement o	f Act 74, Mich. P.A. 19		Received for record the
Gogebic	Located In:	Corner Code		22	day of June
(County)	Ecodica III.	Corner Code	•	A. D. Å	00 at 1:20 o'clock
1. Public Land Survey	т48 ^N R	44W D-11		<u></u>	m., and recorded in
,	TR	SURV		Uber 8	O CORNER
	TR TR			M page	3
2. Property Controlling	S TR		LIVIALION	(Se	ul Ruppe, Dep
in Section	SR		2001		Keduter of Deade
Miscellaneous Property in Sec.	S TR S T R		····		
. ropolly in ooo.	<u> </u>	SECT	<u>ion</u>	Register of D	eeds Stamp & File Number
4. Lot No, Record	ded Plat			Авср	E F G H I J K L 1
Quarter section	orner Sect	ions 20 % 3	2 TV. RN DI. I.W	2 6 5	
·			•	3	
, John P. Goss	in a field survey on	May 25,2000	_ do hereby state that under	4 7 - 8 -	9101112
requirements of P.A. 74, Michigal conformance with regulations and	n P.A. of 1970, the corn- rules therefore as require	er points mentioned in l ed in the current manual	lines 1 and 2 above were in	5	
United States Department of the Inthat the corner points mentioned	nterior, Bureau of Land M	fanagement or by a deci	ree of a Court of Law and /or	6 -18 17	16 15 14 13
Board of Land Surveyors or by	a Decree of a Court of	of Law; established, re	established, monumented,	7	
recovered, found as expressed bel				8 19 20	22 23 24
NOTE: Not more than 2 come on this certificate.	ers, all in the same tow	n and range, may be	recorded	9	
on the certificate.				10 30 -29	28 27 26 25
				11 32 31 32	33 34 35 36
				13	
A. Description of original more Corner established Original bearing Donald D. Lappala bearing and distable iron pipe with 8" Hemlock - N 355" Hemlock - S 73In 1993 J. Garske B. Description of corner evidence of the second of	trees: Hemle Hemle 1, 12585, on ance from the 3" bronze 160 E - 23.0 180 W - 21.3 180 added 8" Heence found and/or me 150 E - 8.22	Burt, in 1. ock 10" S ock 7" N August 3, e remains of tablet. He ft.(down) ft. emlock - N athod applied in resto	848. $25\frac{1}{2}^{\circ}$ E 21 ling 30° W 5.1ing 1972, restored for the two original established the low Hemlock - metal sign properties where the low - 22.95 ring or reestablishing corrections.	corner po ginal BT's. le followin S Ol ^O E - lost - S 35 ft. (out)	ft.) sition at record He set a 2" by g references. 24.0 ft. O W - 2.7 ft. and
On Dec. 9, 1974,				•	Index V-7.
Found both origin	al bearing t	trees now st	tumps at groun	d level.	
I recovered the m	onument as s	set by Lappa	ala and some o	f the corn	er's accessories.
Act 74 research o	n file.	Ŕ	Course Fire	m 6/21/00	
C. Description of monument for From the found m reference object	onument I es	ories established to po Stablished t	erpetuate locating the pos the following	sition of the corner. existing ar	nd new
11" Hemlock		01° E 24.0	9 ft.		F OF MICHIGAN
10" Hemlock	N 3	35° E 8.2	22 ft.		E SAMONIA DA SAMONIA
7" Hemlock 7" Maple	s 7	73° W 21.3	33 ft.	į	JOHN P. X
metal sign post	5 4 S 7		64 ft. 11 ft. to face		* SURVEYOR *
(All measuremen	t taken to n	ail in side	of tree)	- 3	No. 12

Signed by *Gohn C Jose*Surveyor's Michigan License No.____ 23509

Date May 25, 2000

U.S.F.S. No. V-7