Sagebic County 88. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Received for record the For corners in 26th day of MAY A. D. 36.00 at 1110 o'clock GOGEBIC Located in: Corner Code # (County) m., and recorded in T48NR 44W E-9 1. Public Land Survey Of CORNERS SUBVEY & REMonumentation 2. Property Controlling R in Section **JAN 0 5 2**001 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number SECTION 4. Lot No. , Recorded Plat 5. Private Claims 1 Section Corner, Sections 20,21,28 & 29, T48N, R44W I, <u>John P. Goss</u>, in a field survey on <u>April 6 192000</u> hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 7 Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 8 9 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 11 A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austin Burt, in 1848. Original bearing trees: Yellow Birch 8" S 41° E Yellow Birch 16" N 66° W 18 links (11.88 ft.) 17 links (11.22 ft.) Donald D. Lappala, 12585, on Aug. 11, 1972, restored corner by reference post and a stream call, a cedar and yellow birch line trees East of corner also a very old brazed line east and west from corner. He set a 5/8" dia. by 15" long iron pin. He established the following reference objects: At 29.95 ft. West of corner he set a 2" I.D. iron pipe with 3" bronze tablet, stamped to indicated the corner position; 7" Ash - N 55° W - 84.5 ft. (now stub); 9" S. Maple -

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: S 70° W - 83.3 ft.; Power Pole #176 - N 19° W - 66.5 ft. (now out); a metal signost - N85° W - 30.0 ft.; in 1986 J. Garske added a P.Pole #168 - N22°W- 78.25 On Dec. 9, 1974, Lappala recorded said corner in U.S.F.S. Liber, Index No. R-9.

Found Donald Lappala monument and accessories.

Act 74 research on file.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: I replaced the 5/8" by 15" bended iron pin with a 5/8" by 20" rebar with a $3\frac{1}{5}"$ aluminum cap, 5" below surface, stamped to read: T48N, R44W; S-20,S-21,S-28,S-2 aluminum cap, 5" below surface, stamped to read. 140N, 140N, 170N, 22° W Power Pole #168 78.21 ft. new nail JOHN P. N 57° 6" Maple 39.84 ft. GOSS Reference Monument West 29.95 ft.

N 850 W Metal sign post Metal sign post N 850 W 30.0 ft. to face (All measurement taken to nail in side of object)

1" iron pipe in roadway S 05° E - 7.45 ft. from corner. Signed by Aska P Soss Date April 2000

23509 Surveyor's Michigan License No. U.S.F.S. No. R-9 Register's (Mice)

LAND

SURVEYÛR

23509