Register's Office ss. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Received for record the For corners in 26 th day of MAY GOGEBIC Located In: Corner Code # A. D. 10-00 at 11:20 o'clock (County) _m., and recorded in T48NR 44W 1. Public Land Survey E-10 Of CORNERS SURVEY & REMONUMENTATION KL 2. Property Controlling Registat in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number SECTION 4. Lot No. _, Recorded Plat 5. Private Claims Quarter corner, Sections 28 & 29, T48N, R44W I, John P. Goss, in a field survey on April 7, 19 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 9 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate A. Description of original monument and accessories and/or subsequent restoration: Corner established by Austin Burt, in 1848. Original bearing trees: Hemlock 6" S 54° E 5 links (3.30 ft.)

Sugar Maple 12" N 35° W 24 links (15.84 ft.)

Donald D. Lappala, 12585, on August 18, 1972, restored quarter corner by single proportionate measurement in the centerline of Old M-28 between section corners 1/2 mile North and South. He set a 5/8" dia. by 14" long, iron pin. He establised the following reference objects: At 24.00 feet West of corner he set a $2\frac{1}{2}$ " I.D. iron pipe with 3" bronze tablet, stamped to indicated the corner position 6" Elm - N78°E - 37.3 ft. dead; 10" Elm - S45°E - 54.2 ft. dead; P.P. #167

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M.S.P.-N82°W-22.2 ft. N79°W - 24.6 ft. cut down; in 1986 the following were added: 18"W.Pine-N66°W 85.20 ft.; 9"R.Maple - S61°W - 96.95 ft.; P.P.#159 - N63°W - 36.42 ft. On December 9, 1974, Lappala recorded said corner in U.S.F.S. Liber, Index #T-Found Lappala monument and accessories and the added accessories. Act 74 research on file. Richard P. Drahm 05/24/00 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2" below surface I placed a 3½" aluminum cap over the 5/8" iron pin, cap stampe to read: County Remonumentation; T.48 N., R.44 W., 1/4; S-28, S-29, 2000, P.S. 23509. From which I established the following existing and new reference object Reference Monument

West 24.00 ft.

24" White Pine N 66° W 85.52 ft.

> FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197 REVISED MAY 14,197 REVISED JAN., 198 REVISED OCT., 198

Date April 7, 2000

97.25 ft.

36.28 ft。

22.2 ft. to face

s 61° W

N 630 W

N 820 W

(All measurement taken to new nail in side of object)

23509

U.S.F.S. No. T-9

ll" Red Maple

Power Pole #159 Metal sign post

Signed by John. P. Loos

Surveyor's Michigan License No.

JOHN P.

GOSS

LAND

SURVEYOR