SEP 0 8 1998	EP 0 8 1998			Register's Office ss.				
	LAND CORNE	R RECORDATION CERT	GEICATE	igebic tou	,			
SECTION For corners in		ement of Act 74, Mich. P		Z3 Rec	eired for _day of_	recon	rd the <u>나무</u>	ŧ
Gogebic County	Located In:	Corner Code ##	Å	. D. 19 <i>A&</i>		40	o'clock	
Public Land Survey	T 48NR 45W T R T 48NR 46W	A-8 M-8		iber 7 a page 3 Rannon	oL <u>3</u> oL	Mo.	DOP	25
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R	0	Register of	f Deeds Sta	Regist	٠,		
	ecorded Plat		A	BCDE	F G H	i j	K L	L T
	24; T.48 N., R.45		3	5	-43- - 	—- ½	!——	+
do hereby certify that under requingling lines 1 and 2 above were in current manual of survey instructions and erree of a sangement or by a decree of a sangement or by a sang	in a field survey on <u>July</u> irements of P.A. 74, Michigan P.A. conformance with regulations and tions of the United States Depart Court of Law and/or that the corne the rules of the Michigan Board oestablished, monumented, re-n	of 1970, the corner points menti d rules therefore as required i ment of the Interior, Bureau of r points mentioned in lines 3, 4 f Land Surveyors or by a Decre	ioned 6 10 11 11 11 11 11 11 11 11 11 11 11 11	3 17 20	- 9	1,2	3——	13
•	rners, all in the same town an	d range, may be recorded	11	29	28 -27-	20	-	36
A. Description of original m	onument and accessories and	l/or subsequent restoration	13		ıı l	<u> </u>	<u> </u>	Ţ
Corner position retump holes of the corecovered line aluminum pipe 14" Yello 11" Sugar 10" Red M Steel B. Description of corner evi	sign rail East dence found and/or method a	16" N.25 E. 50 L. Drahn (21564).s and from district ature and section and section 22.45' 20.37' 29.37' political in restoring or reestal	links (334) on 8/15, cances north corners and the following corner:	.00') - /84 fro th and s. He llowing	m the south set a		₹	
	n Gogebic County I n file with Gogebi			/84.				
Recovered the mon 18" Yello 13" Sugar 13" Red M	ument as described w Birch N.07 E Maple S.61 E	and the bearing 22.47' 30.88'	, trees as	follow	s:			
Only stump holes :	remain from the or	iginal B.T.s						
	for corner and accessories e	stablished to perpetuate lo	cating the position	on of the co	orner:			
-	tree referenced:			-	A H	Mar.		
8" Basswo				A	of Mic		1	
Resource grade GP	5 Lat. 46-32-32 Long. 89-59-22			* \$ L	DRAHN LAND IRVEYOR		**	

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAH. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Date <u>July 19,1998</u>

Surveyor's Michigan License No. 21564