SURVEY & REMONUMENTATION

JAN 05 2001

	١.	
SEC	TI	ON

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office Sessbie Conuty

Received for record the 25 th day of 406031 A D. Woo at 1:20 o'clock WHOI B OF CORNER 31 page 12 Ramona Collina Deputy Register of Books

Corner Code # Located In: <u>-Gogebic</u>

1. Public Land Survey

For corners in

15W

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

	1 - 1 211(-12 71)	
S	TR	
S	TR	
s	TR	
6	T P	


Register of Deeds Stamp & File Number

___ , Recorded Plat __ 4. Lot No. 5. Private Claims _

Section Corner 5, 6, 31 & 32; $\frac{T}{20}48-49$ N., R.45 W.₃

I, <u>Richard I.</u> <u>Drahn</u> in a field survey on <u>Aug. 16.19 O</u>to hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Austin Burt on 9/9/1847. Original B.T.s: (25,08)

Sugar

10"

N.64 E.

38 links

Y. Birch

18"

N.21 W.

52 links

(34.321)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I restored the corner position at record bearing and distance from the windthrown stump holes of the two original bearing trees. Distances east, west and south 2 mile to recovered corners is in accord with the field notes of the original Government survey.

A $1\frac{1}{4}$ " iron pipe, source unknown bears S.87 W., 9.0' from the original corner location.

Corner research on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2" X30" aluminum pipe with a $3\frac{1}{4}$ " stamp aluminum cap and the following new bearing trees:

2.58' 12" East Yellow Birch 8" 29.36' S.67 W. Yellow Birch 811 15.62' N.14 W.

Sugar Maple 6 1 S.36 W. 1.98' Steel sign rail

L. DRAHN LAND SURVEYOR No. 21564

RICHARD

August 17, Date _

USFS A-5

Surveyor's Michigan License No.