## SURVEY & REMONUMENTATION

## JAN 05 2001

SECTION For corners in	LAND CORNER RECORI Filing Requirement of Ad		70 Segebic County		
Gogebic   Located In:   Corner Code #			Received for record that		
			P Lilber_	A. D. 19 co at 1/20 o'clock  P. m., and recorded in Liker 8 of Corners	
2. Property Controlling S T in Section S T 3. Miscellaneous S T Property in Sec. S T	3. — —	Register of Deeds Stamp & File Number			
4. Lot No, Recorded Plat 5. Private Claims			ABCDE	FGHIJKI	<u> </u>
Section Corner 4, 5, 32			2 6 5	<b>-4-</b> 3- 2	   
I, <u>Richard L. Drahn</u> in a field sun requirements of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules therefore as United States Department of the Interior, Bureau of that the corner points mentioned in lines 3, 4 and 5 Board of Land Surveyors or by a Decree of a recovered, found as expressed below:	he corner points mentioned in lines required in the current manual of s Land Management or by a decree of above were in conformance with the	s 1 and 2 above were in curvey instructions of the of a Court of Law and /or he rules of the Michigan	4 7 8 5 6 18 17 7 8 19 20	- 9 - 10 - 11 - 1 -16 - 15 - 14 - 1 -21 - 22 - 23 - 2	3-4-
NOTE: Not more than 2 corners, all in the sai on this certificate.	me town and range, may be reco	orded	9 10 30 29 11 12 31 32	-28 -27 -26 -2 -33 -34 -35 -3	5
A. Description of original monument and acc	nossorios and/or subsequent re	ectoration:	13		Ĺ
Original corner establi Sugar 9 Sugar 12	" N.21 E.	art on 9/9/18 32 links 36 links	47. Origin (21.12') (23.76')	al B.T.s:	
B. Description of corner evidence found and I restored the corner policy holes of the two origins "Ascend ledge, 20 ft., recovered quarter corner Government survey. A decorner bears S.85 E., 6 Corner research on file	osition at record al bearing trees. WSW" and the 40.0 rs is in accord wowned 6" Sugar Ma .0 ft. from the c	t bearing and The 2.00 con the 2.00 con the district the field aple, squared priginal corn	distance f hain distan ance east a d notes of and painte	nd west to the original	\$ 4.
C. Description of monument for corner and a	accessories established to perp	etuate locating the posi	tion of the corner:		
At the corner position aluminum cap and the formal sugar Maple 60 Sugar Maple 90 Sugar Maple 40 Steel sign rail 60	I set a 2" X 30" llowing new beari " N.27 W. " S.52 E. " S.48 W. " N.58 E.	aluminum pipo	e with a 3½	RICHARD L. DRAHN LAND SURVEYOR	***
0.0000	16 <u>cka</u>	elt. Wedn 8/	23/00	TAND CO	5
Signed by <u>Kirchard L. Mar</u> Surveyor's Michigan License No. 2156	ahn 31	Date	August 17,2	000	
USFS A-9	<del> </del>				