MAR 02 2000

	ĒC	4	1	± 5
	P .	6 6	7 B	10 I
- 1	Breez No.	יובותי		W

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's tiffice See Gegebic County See.
Received for resord the
A. D. 1999 at 1:45 o'clock  Pm., and recorded in
ther 7 of CORNERS
Ramona Collins. Departy Register of Double

1. Public Land Survey

Gogebic

For corners in

Register of Deeds Stamp & File Number

2. Property Controlling in Section

3. Miscellaneous
Property in Sec.

5. Private Claims \_

4. Lot No.


Recorded Plat	 	 

Quarter Corner 13 & 18; T.48 N., R.44-45 W.

S

I, <u>Richard L. Drahn</u>, in a field survey on <u>July 11</u>, , 19 94 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Austin Burt on 9/8/1847. Original bearing trees:

Sugar

12"

S.83° W.

9 links

(5.94')

Hemlock

6"

N.66° E.

21 links

(13.86')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence remains of the original corner or accessories.

Corner position re-established by single proportionate methods, on line between and equal distance from the northeast and southeast corners of section 13, T.48 N., R.45 W.

Corner research on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2" x 30" aluminum pipe monument with a 3 1/4" stamped aluminum cap and the Following new B.T.s (all measurements taken to a nail in side of tree)

Sugar Maple

13" 10" N.30° W.

4,92"

Sugar Maple Sugar Maple

Surveyor's Michigan License No.

12"

N.71° E. S.35° E.

21.44' 13.94'

Steel sign rail

6,

S.47° W.

21564

2.02

PEER GROUP APPROVAGE

COUNTY WINDSHALLING

RICHARD
L. DRAHN
LAND
SURVEYOR
No.
21564

Signed by Richard L. Wzah

Date <u>August 10, 1999</u>

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL

REVISED MAY 14,1975 REVISED JAN., 1983

USFS L-25

REVISED OCT., 1996