SURVEY & REMONUMENTATION

SEP 0 8 1998

Surveyor's Michigan License No._

23509

Fed. No. N-7

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office	
Register's Office Gogebic County	58

,
Received for record the
14 day of MAY
A. D. 19 18 at 3:20 o'clock
/
Page 392 Ramona Colum Olg. Register of Deeds
Ramona Collins Dep.
Register of Deeds
•

For corners in SECTION	V				day of	
Gogebic	Located In:	Corner Code #		A. D. 19	10 at 3:20	
(County)					m., and re	
1. Public Land Survey	T <u>48NR46W</u>	<u>D-7</u>		Liber 6		ORNERS
	TR				392	ν
	TR			Kame	ma Collin	
2. Property Controlling	S TR				regisser	of Deeds
in Section	S TR		ļ			•
3. Miscellaneous Property in Sec.	S 'R			Denictor of	Deeds Stamp &	File Number
Property in Sec.	· ·			Vehister of	Decus Otalilp w	The Hamber
	ded Diet					
4. Lot No, Record	ded Flat		1	A B C D	E F G H	I J K L M
1/4 cor. comm.	to Sec's. 17 8	c 20, T.48N., R	.46W 2	2 - 6 - 5		
•				3		
John P. Goss	, in a field survey on Ma	ren 7, 19 90 do hereby	state that under 4	4 - 7 8-	9-10- 	
requirements of P.A. 74, Michiga	n P.A. of 1970, the corner po	the current manual of survey ins	structions of the		16-15-	14 13
United States Department of the I	nterior, Bureau of Land Manag in lines 3, 4 and 5 above were	in conformance with the rules	of the Michigan	7	16-1-15	
Board of Land Surveyors or by	a Decree of a Court of La	w, established, re-established	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	8 19 20	21 22	23 24
recovered, found as expressed be				1 1 2		
NOTE: Not more than 2 com	ners, all in the same town ar	d range, may be recorded		10-30-29	2827	26 -25
on this certificate.			1	11		
			1	123132	33 34	35-36-
Description of original mo			1	13		
on May 22, 197 and distances and the second stamped to ind reference obje 7" Sugar Maple 5" Sugar Maple 5" Sugar Maple 7' Metal sign He recorded sa Found Richard I updated the county specifi Act 74 researce	ng trees: Suga Suga 5 Richard Drah from remains o a sugar stump icated the cor cts. N 380 E 2 idence found and/or meth S 700 W Post S 890 W id corner in I Drahn corner m corner monument cation.	r 10" S 100 W r 10" N 10° E n, RLS, restore f original bear hole. He set a ner position. I 0.2' od applied in restoring or re 7.3' (now bend 1.9' tiber 1, page 1 nonument and wi at and accessor	3 links. 3 links. ed corner ring trees a 2½" iron He establi establishing come over and s 76 of Land tnesses. ies as not	position One a pipe wi shed the plit) Corners ed below	at recording the 3" broke following for Gog w to state 1/3/98	rd bearing ple stump onze cap ng
C. Description of monumen	nt for corner and accessori	es established to perpetuat	e locating the posi	tion of the cor	ner:	r • 1/1.•
From the 2½ is S-17, S-20, R.I bearing trees	on pipe with	75, from which	nich reau:	TAMO N	** Treate in	and new
8" Sugar Maple 6" Sugar Maple 5" Sugar Maple 7' Metal Sign I	S 33° E S 61° W	20.30' 6.47' 16.34' 1.9' (to face			* *	DHM P. A
(All measuremen	-		•		SI	URVEYOR No. 23509
	.= .4 \$. /	11.	MANTERE	THE STATE OF
Signed by Goh	n P y or	<u> </u>	Date4//	1/98	.4899	Million