•			
			Register's Office sa.
	I AND CODN	ED DECORDATION CERTIFIC	
		ER RECORDATION CERTIFICA	
For corners in	Filing Requir	ement of Act 74, Mich. P.A. 19	
		1	A. B. 19 45 at 10:10 o'clock
Gogebic	Located In:	Corner Code ##	A m., and recorded in
100071171		1	Liber 5 of CORNERS
1. Public Land Survey Sec	. 5 147N R 46W	D-1	-
Sec	. 32 T48N R 46W	D-13	m page 287
	- TR		Ramora Collins, Deputy
	T R		Register of Deeds
• • •	S T R		,
	S T R		
	3 T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		<u> </u>
A	and Dist		
4. Lot No, Reco			A B C D E F G H I J K L
5. Private Claims			
1/4 cor. comm. t	o Sec. 5. T.47N	R.46W.	3 1 1 1 1 1 1
 , , 	Sec. 32, T.48N	r. R.46W	4
I. John P. Goss , in			5 1 1 1 1 1
do hereby certify that under require	ments of P.A. 74. Michigan P.A.	of 1970, the corner points mentioned	
in lines 1 and 2 above were in co.	nformance with regulations ar	nd rules therefore as required in the	6 18 17 16 15 15 14 13
current manual of survey instruction	ons of the United States Depar	rtment of the Interior, Bureau of Land	7
		er points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
above were in conformance with the	e rules of the Michigan Board (of Land Surveyors or by a Decree of a monumented, recovered, found as	9
expressed below:	Approved, Monarcon, 12		10 30 29 28 27 26 25
NOTE: Not more than 4 corn	ers, all in the same town a	nd range, may be recorded	11
on this certificate.	 ,		12 31 32 33 34 35 36
			13
Original bearing	established by W trees: Y. Bird Hemlock	Villiam A. Burt in 1 ch 14" N 79° E 49 c 14" N 09° W 21	links
checked with mea this corner in the established the	surement to cree iber 2 on page ; following witnes	ek and several plats	iron pipe in concrete in area. They recorded for Gogebic County. They 14" Elm- N 80° W- 18.83';
This corner was this corner usin	removed in const ag plat monument and other plat ti	applied in restoring or reestablish truction in 1989. Join area in 1992. It ies. I updated the county spec	ohn R. Garske replaced checked with the orner monument and

Act 74 reseach on file with the County Register of Dedds Office

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I cemented a 5/8 inch rebar 9 inches long into the rock outcrop. I placed a 3½ " aluminum cap on the 5/8 " rebar stamped: County Remonumentation; T. 47-48 N; R.46 W., 1/4; S-32, S-5; 1995, P.S. 23509. I established of Manual County Remonumentation. OF MICHIGAN following bearing trees and reference objects. 95.061 n 67° E 6" Maple

S 77° E 12" Maple 88.561 Due West Due East Conc. Mon. & 2" rebar. 16.001 3.661 Railroad spike Reference Monument consisting of 21 x 30" aluminum monument with a $3\frac{1}{4}$ " aluminum cap 6' steel rail & sign-at l. stamped to indicate corner position: \$150 W-64.00' with 6' steel rail & S 150 W-64.00'

July 31, 1995

Surveyor's Michigan License No.

P.S. 23509

SURVEYOR

1/4 cor R.R. Spike 1/2" reb. Ove West 4. RAIL ASIGN

1-