MAR 0 2 2000

Register's wifee Cogebie County SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Received for resert t 2155 day of JULY For corners in A. D. 1999 at 1:25 o'dock Gogebic Located In: Corner Code # (County) m., and recorded 1. Public Land Survey 1 page 204 Ramona Calling Deput Legister of Bond 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. _ _,Recorded Plat _ 5. Private Claims 1/4 corner 15 & 16, T48N, R46W 2 3 i, <u>John P. Goss</u>, in a field survey on <u>May 24</u>, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the 4 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 8 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Corner established by Austin Burt on June 4, 1851. Original B.T.'s: Fir 10" S 30° E 12" N 46° W 10 links (6.601)Cedar 12" N 46° W 19 links (12.54')
On March 14, 1979, Richard L. Drahn found correct corner position marked by portion of a 3" Sq. cedar picket in a mound of stones at record bearing and distance from the remains of the cedar bearing tree. He set a 2" x 5' iron Cedar pipe with 3" brass cap stamped to indicated the corner position. He established the following ferences objects: 13" Cedar - S 470 W - 27.5 ft.; 9" Cedar (down) N 140 W - 6.45 ft.; 5" Cedar (Down) N 820 E - 25.55 ft; 10" Black Ash - N 820E B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 7 metal sign post - N 87° E - 1.3 ft. 27.3 ft.: He recorded said corner in Liber 2, page 27 of Land Corners for Gogebic Co. Found Richard L. Drahn, monument and accessories. Act 74 research on file. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From found monument I established the following new and existing reference objects: E OF MICHIGAN 16 Cedar S 470 W 28.20 ft. new nail 12" Black Ash N 820 E S 610 E 27.47 ft. new nail 9" Black Ash 14.13 ft. 7' metal sign post N 87° E GOSS 1.3 ft. to face (All measurement to nail in side if tree) Signed by John P Doso Date May 24, 1999 Surveyor's Wichigan License No.____

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

U.S.F.S. No. L-13