. '	LAND CORN	ER RECORDATION CERTIFICA	Register's Office ss. Gogebic County ss. Received for record that
		rement of Act 74, Mich. P.A. 19	Meeting tot record
For corners in	•		A. D. 19 93 at 12:20 o'clock
Gogebic	Located In:	Corner Code ≠≠	P m., and recorded in
			Liber 4 Of CORNERS
Public Land Survey Sec	tion 4 T <u>47N R 46</u> W	<u> </u>	on page 323
	R		Betty Spare Deputy
2. Property Controlling	S I B	<u>G-13</u>	Hegister of Beeds
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No, Re	corded Plat		A B C D E F G H I J K L M
5. Private Claims			
Section corner common to S-4 & 3, T47N, R46W and S-33 & 34, T48N, R46W.			
¥ 1011, 1110 11		ecember 7 93	4 7 8 9 10 11 12
		of 1970, the corner points mentioned	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawand/or that the corner points mentioned in lines 3, 4 and 5			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			
Hote. Not more than 4 borners, an in the same town and range, may be recorded			11
on this certificate.			12 31 32 33 34 35 36
A. Description of original me	onument and accessories an	d/or subsequent restoration:	. 13
Original surve birch bears N2	y by Austin Burt on Septe 24°E, 33 links and a 10" h	ember 9, 1847. Set black ash p emlock bears N65°W, 21 links	oost from which an 8" Y.
No original ev	idence found.		
			•
B. Description of corner evid	dence found and/or method	applied in restoring or reestablishi	ng corner:
ancient fence li	ines running east and wes	enter line of North Moore Road t. This location is consistent w	ith natural feature ties and
checks closely	with dimensions taken fr	om 1920's era Soo Line Railro	ad plans with ties taken with
also were used	to verify this corner posi	en to known corner positions to tion. This position is marked l	o the east, west and south
been used in se	everal surveys of record a	nd accepted by the Road Comm	nission as the section
corner.			TE OF MICE
	PEER GROUP APPR	Oven	JOHN R.
1		16/95	GARSKE \
	COUNTY BEFRESEAT	TIVE	LAND SURVEYOR
C. Description of monument	for corner and accessories	established to perpetuate locating	No.
D. 1 1 6	1 70 TZ - 15 - 1-5		TO LAKO SUS
hearing trees ar	nd P.K. nail with a cottor nd reference objects:	spike set below road grade. F	stablished the following
	1 - N27°-30'E - 68.24 feet	t	
10" ash - S86°E - 33.27 feet Power pole #33-94/11 - S69°W - 35.05 feet			
Reference monument - N60°W - 30.40 feet - Set standard Bernsten 2.1/2" aluminum pine v			
30" long with 3 1/2" aluminum cap stamped and a steel sign post - north - 0.88 feet			
Reference monument - S39°W - 65.55 feet - Set standard Bernsten 3 1/2" stamped aluminum cap on a 3/4" x 30" rebar, steel sign post - 0.91 feet			
	Im can on a 2/4" = 20"1	har steel sion mark 0.01 C	on o 1, 2 backiped
	Im cap on a 3/4" x 30" rel	bar, steel sign post - 0.91 feet	•
Signed by Signed by	Im cap on a 3/4" x 30" rel	bar, steel sign post - 0.91 feet Date 12/2	•