	LAND CORNER RECORDATION CERTIFICATE		Goge ATE	Gogebic County ss. Beceived for record the			
Filing Requirement of Act 74, Mich. P.A. 1970				30 Th day of December			
Gogebic	Located In:	Corner Code ##	A. D	A. D. 19 43 at 12:30 o'clock Pm, and recorded in			
(County)							
1. Public Land Survey Sect		<u>I-1</u>	Liber			ORNKRS	
	T R			11 34 11 1	7	D n t	
Property Controlling in Section	S T R S T R	<u>I-13</u>)	4.1.0	ay,s	Register	of Boods	
3. Miscellaneous	S T R		Register of I	Doode St	ama & Eil	a Number	
Property in Sec.	S R		negister or i		апратп	e Muniber	
4. Lot No , Red	corded Plat		A R	C D E	FGH	IJKLI	
5. Private Claims			—	ĭĭī	- 	† 1 1 1 1 1 1	
Section corner S-34 & S-35, 3	common to S-2 & S-3, T ² [48N, R46W.	17N, R46W and	3	5-	- à - 1 - à - - 1 - 1 - 1		
. Takin B. Gannales	Dec	cember 27 493	4 - }-	┼-	- 910-	11-12-	
i, <u>John R. Garske</u> , i	in a neid survey on	of 1970, the corner points mentioned	5	 - - 	- - - 		
		d rules therefore as required in the		+-1/	-1615-	1/4-1-1/3-	
-	•	ment of the Interior, Bureau of Land	7	+++			
		r points mentioned in lines 3, 4 and 5	· · · · · · · · · · · · · · · · · · ·	20	-2122-	23 24	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				╅╾╁╌╂	+++	 	
expressed below:			10 -30-	29	-2827-	2625	
NOTE: Not more than 4 core	ners, all in the same town an	d range, may be recorded	11	+-+-+	111		
on this certificate.	*		12 31-	32	-3334	3536	
A. Description of original mo	nument and accessories and	/or subsequent restoration:	13	111		<u> </u>	
		r 9, 1847. Set sugar post fro	m which a	20°° வச	ar hears .		

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence found. Found a 6" nail at the intersection of a two-track road to north and an old North-South fence line to the south and at the center line of Stone Road. This corner position has been used in several surveys and is generally accepted as the most probable location of the original section corner by both local surveyors and area residents. Due to the history of the cornr location and its general use and acceptance, I am accepting it as marking the true section corner location.

N62°E - 34 links and an 8" hemlock bears N57°W - 29 links and a 10" sugar bears S65°W - 19

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner 28410

Replaced the nail with a 3/4" x 30" iron rod with a stamped 3 1/2" diameter aluminum cap from which I established the following bearing trees and reference objects:

18" apple - S39°E - 40.36 feet

links.

5" basswood - N19"W - 34.40 feet

Reference monument - N25°E - 34.89 feet. Set 2 1/2" x 30" aluminum County Monument

with a 3 1/2" stamped aluminum cap - steel sign post - 1.33 feet.

Reference monument - S57°W - 47.78 feet. Set 2 1/2" x 30" aluminum County Monument with a 3 1/2" stamped cap - steel sign post - 1.96 feet.

Surveyor's Mijchigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. REVISED MAY 14, 1975 REVISED JAN. 1983

Register's Office

JOHN R. GARSKE LAND SURVEYOR