SURVEY & REMONI IMERIT

OCT 0 3 1996

4. Lot No. 5. Private Claims _

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register'	s Office	١.
Register' Gogebic	County	} \$\$.

Recei	ved for record the
1679	day of <i>Corners</i>
	at 10:30 o'clock
	, and recorded in
	O CORNER
- May 40	4
Ramona Co	4 Um Depaty
,	Poriation of D

Register of Deeds Stamp & File Number

For corners in		Filing Require	Filing Requirement of Act 74, Mich.	
	Gogebic (County)	Located In:	Corner Code ##	
1.	Public Land Survey	1 48N R 47W T 48N R 48W	A-5 M-5	
2.	Property Controlling	T R ST R		
	in Section	S R		
3.	Miscellaneous Property in Sec.	S T R S T R		

___ , Recorded Plat _

July 23 I. John P. Goss in a field survey on ___ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

Section corner 12,13,7 & 18; T.48 N., R.47-48 W.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: Original corner established by William Burt, in 1847.
Original bearing trees 1. Spurce 9" N 18° E 40 li
2. Hemlock 16" S 47° W 23 li
3. Hemlock 14" S 68° E 55 li
4. Spurce 8" N 62° E 31 li

40 links (26.40') 23 links (15.18')

55 links (36.30') 31 links (20.46')

4. Spurce 8" N 62° E 31 links (20.46')

Richard L. Drahn & John P. Goss, both R.L.S. restored the corner position at record bearing and distance from the remains of the original bearing trees. At the corner position they set a 1½" I.D. by 4 foot long, concrete filled, iron pipe, capped with a 3" circular brass table which reads:

T.48 N., R.47-48 N.; S-12, S-13, S-7, S-18; 1978; R.L.S. 23509. From which Description of corner evidence found and/or method applied in restoring or reestablishing corner:

they established the following new blazed and scribed bearing trees:

they established the following new blazed and scribed bearing trees:
10" Hemlock N. 120 W. 20.6' And
12" Hemlock S. 880 E. 28.0' recorded said corner in Liber 1 on recorded said corner in Liber 1 on pages 3" Red Maple S. 420 W 402 and 403 of Land Corners for Gogebic

County.

I found the lin I.D., iron pipe with 3" Circular brass table and it checked with Drahn and Goss witnesses. I updated the accessories as noted below to state and county spec ification. All of the evidence found in 1978 survey still at this location.

Act 74 research on file.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the $1\frac{1}{2}$ " iron pipe with 3" brass table, I established the following existing and new bearing trees and reference objects.

N 120 W 20.60 14" Hemlock S 88° E S 42° W N 56° E 16" Hemlock . 28.01 4" Red Maple 27.64 N 56° E N 03° W 7.881 6" Hemlock 1.12' 6 rail & sign



Surveyor's Michigan License No.

23509