REMONUMENTATION

OCT 0 3 1996

COMMISSION

AND CORNER RECORDATION CERTIFICATE

Register's Office Gogebic County

e.'	Filing Requirement of Act 14, which, P.A. 1970		
For corners in Gogebi	c Located In:	Corner Code #	28 th day of MARCH
(County)			A. D. 1996 at 11:25 o'clock
Public Land Survey	T 48N R 47W		A ni., and recorded in Uber 5 of Corners
	T R T R		Ramona Collins, Deputy
Property Controlling In Section	ST R ST R	•	Register of Deeds
3. Miscellaneous	S T R		m
Property in Section	S T R		Register of Deeds Stamp & File Number
4. Lot No, F	Recorded Plat		A B C D E F G H I J K L N
5. Private Claims			
Section corner common to Sections 28, 29, 32 & 33, T47N, R46W			3
John R. Garske	in a field survey on	nuary 15 , 19 96	4 7 8 9 10 11 12 12 1
do hereby certify that under re- in lines 1 and 2 above were in a	quirements of P.A. 74, Michigan P. conformance with regulations and i	A. of 1970, the corner points mentionerules therefore as required in the currenent of the Interior, Bureau of Lar	nt - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a			
		ited, re-monumented, recovered, four	
NOTE: Not more than 4 co on this certificate.	rners, all in the same town and	i range, may be recorded	11
A Description of criminal	manument and accompains	and/or eubsequent restoration:	13

- - In 1848 William Ives, U.S. Deputy Surveyor, set a wooden post from which a 14" hemlock bears N08 W 11 links (7.26 feet) and a 15" sugar - S45°E - 34 links (22.44 feet).
 - On Dec. 14, 1983, John R. Garske, RLS 28410, reestablished the corner position as recorded on February 8, 1984, in Liber 2 of Land Corners, on Page 563, the corner consisting of a P.K. nail at the centerline of Junet and Airport Roads from which the following reference objects were established: Fence post - N47°W - 60.92 feet, power pole -N39°E - 39.62 feet, power pole - S74°W - 128.25 feet.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found P.K. nail 1 1/2" below asphalt road surface and checked with the one available witness (power pole - N39°E -39.62 feet) also checked with a distance south to the monumented section corner.

I updated the corner position to State and County specifications as noted below.

(P.A. 74 Research on File)

GARSKE LAND SURVEYOR 28410

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

I replaced the found P.K. nail with a stamped brass cap from which I established the following reference objects:

Power pole - N39°E - 39.62 feet (existing)

Power pole - S54°W - 56.82 feet

Guy pole - N63'W - 56.57 feet

Reference monument consisting of a 2 1/2" dia. x 30" long aluminum pipe with a 3 1/4" diameter aluminum cap stamped: County Remonumentation; T48N, R47W, S-29, S-28, S-32, S-33; 1996; RLS 28410; R.M., N45°W -48.92 feet; set 6 foot steel rail with sign 0.90 feet away.

Signed by 28410 Surveyor's Michigan License No.

REVISED JAN., 1983