SURVEY & REMONUMENTATION

OCT 0 3 1996 Register's Office Gogebic County COMMISSION LAND CORNER RECORDATION CERTIFICATE Received for record the Filing Requirement of Act 74, Mich. P.A. 1970 For corners in 28th day of MARCH Gogebic Located in: Corner Code # A. D. 19 96 at 11:35 e'clock A n., and recorded in T 48N R 47W 1. Public Land Survey OF CORNERS 342 2. Property Controlling Т in Section T 3. Miscellaneous T Register of Deeds Stamp & File Number Property in Section _ , Recorded Plat _ Private Claims One-quarter corner common to Sections 32 and 33, T48N, R47W. John R. Garske January 15 . in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: - In 1848 William Ives, U.S. Deputy Surveyor, set a post from which a 14" lynn bears S46°W - 36 links (23.76 feet); and a 14" sugar - N28°E - 22 links (14.52 feet). - On December 14, 1983, John R. Garske, RLS 28410, reestablished the corner position consisting of a P.K. nail from which a power pole bears N12°E - 62.58 feet; power pole - S85°W - 44.27 feet; and a P.K. nail - due north -6.58 feet. Recorded Liber 2, Pg. 561 of Land Corners.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of the reestablished corner position from 1983 could be found due to road reconstruction. Reestablished the corner position at proportional distances between opposing section corners and monumented this position to State and County specifications as noted below.

(P.A. 74 Research on File)

Richard Long 3/27/96
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

The corner position is marked by a P.K. nail in the centerline of Junet Road from which I established the following reference objects:

Telephone Pole #M-78 - N12'E - 62.85 feet Power Pole #32-93/50 - S83'W - 44.56 feet

Two reference monuments each consisting of a 2 1/2" dia. x 30" long aluminum pipe with a 3 1/4" dia. cap stamped:

County Remonumentation; T48N, R47W; 1/4; R.M.; S-33; S-34; 1996; RLS 28410

R.M. #1 - N83°E - 28.79 feet with 6' steel rail with sign 1.0 feet away

R.M. #2 - S45°E - 44.18 feet with 6' steel rail with sign 1.0 feet away

SEE SKETCH ON BACK	
Signed by Rauke	Date 3-27-96
Surveyor's Michigan License No. 28410	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28,

JOHN R. GARSKE

LAND SURVEYOR No. 28410 OCT () 3 1996

COMMISSION

5 KETCH No Scale

