-SURVEY & REMONUMENTATION

JUN 2 9 1995

COMMISSION

ND	CORNER	RECORDATION CERTIFICATE	Cogebie	C
na	Requirem	sent of Act 74 Mich PA 1970		R.

		2302.	LAND CORNE	IN RECOMPATION CENTIL	FICATE	A.2			,				
- - -	r corners in		Filing Require	ement of Act 74, Mich. P.	A. 1970				inad (
U				1					day e				
	Gogebic (County)		Located In:	Corner Code ##		A	ù I	395	Rt /	:30	_s't	OCE	
١.	Public Land Survey	S-15	48N 47W. T <u>47N</u> R 48W T R T R	<u>H-5</u>			<i></i>		n., 80	ते रक	ordec	i h	
			T R			Ra	m	ma	Call	ins	يھر	δū	tu
2.	Property Controlling	S	T R			-			Reg	istar	of I	GGG	, 0
	in Section	S	T R										
3.	Miscellaneous	s _	T R		Regis	iter o	f De	eds S	tamp	& File	Nur	nber	
	Property in Sec.	S	T R	<u>.</u>									
	•												
4.	Lot No	, Recorde	d Plat			A	вс	D	E F	G H	ı j	K	L M
ō.										\Box	\top	\top	
	One quarter corner co	ommon to	Sections 10 & 15, T48N	, R47W		2 - 4	1	5 	4	3- 	十 i	1	-1
	·					3	\vdash			 	+	\dashv	+
			1.6		:	4	7	- 8	— ģ —	10	+-1	<u>'</u>	—(2
. ~	John R. Garske	_ , in a fi	eld survey onM	arch 29 , 19 95	<u> </u>	5	-+			Ι-Φ-	+	+	
ioi	hereby certify that under	requiremen	its of P.A. 74, Michigan P.A. mance with regulations an	of 1970, the corner points mentic d rules therefore as required in	onea o the	6 -1	8	— 17——	16	15	+-1	4—	13
:14F	rent manual of survey ins	structions of	of the United States Depart	ment of the Interior, Bureau of L	and	7	┷			$\vdash \vdash$	-	\dashv	
Лa	nagement or by a decree	of a Court o	f Law and/or that the corne	r points mentioned in lines 3, 4 a	ind 5	81	 	_ _20—	│ ├─21──	! 22	1_2	3—	_ _24
bc	ove were in conformance	with the ru	les of the Michigan Board o	f Land Surveyors or by a Decree	e of a	9			LL	$oxed{oxed}$			
		, re-establ	ished, monumented, re-n	nonumented, recovered, found	d as	10						ا ،	_ _25
	pressed below:					$\prod_{i=1}^{3}$	ĭ	29 	 		Ti	<u> </u>	
40			all in the same town ar	nd range, may be recorded							\top		
	on this certificat	te.				12 -3	; - 	-32	3 <u>'</u> 3	 3 4	3	<u>-</u>	36 I
۸.	-			d/or subsequent restoration: ion post from which a 12" sug		13 L 11°E,	15 1	inks a	nd a 6	" sugr		1-	
	N53°Ŵ, 41 links.												

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I established the corner position by measurements from existing corners and is positioned on centerline of a paved road at the extension of ancient fence lines running north and south.

Record research on file with Register of Deeds.

REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I set a 3 1/4" diameter brass cap stamped: T48N, R47W; 1/4; S-10; S-15; 1995; RLS 28410, from which I established the following bearing trees and reference objects: 6" basswood - N45°E, 47.19 feet; 16" sugar - S45°E, 70.05 feet; 10" R. pine -N41°W, 39.05 feet; a reference monument consisting of a 2 1/2" diameter x 30" long aluminum pipe with a 3 1/4" diameter aluminum cap stamped: County Remonumentation; T48N, R47W; R.M.; 1/4; S-10; S-15; 1995; RLS 28410; N29°E, 44.53 feet; 6 foot steel rail with sign - 1.70 feet away.

<u> 284</u>10 Surveyor's Michigan License No. .

No. 28410

REVISED MAY 14, 1975 REVISED JAN., 1983

JOHN R. GARSKE LAND SURVEYOR