SURVEY & REMONUMENTATION

JUN 2 9 1995

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code ##

Register's tillion Gogetic Loung	38.
Beceive	for record the
A A 1995 pt	1:30 s'ulock
Liber 5	CORDERS
Ramona Co	Wins Deput

Located In:

Register of Deeds Stamp & File Number

	Lot No, Recorded Plat		
•	Section corner common to Sections 10, 11, 14 ar	nd 15, T48N, R47W.	•
I, _	John R. Garske , in a field survey on	March 29	, 19,

In a field survey on March 29, 19, 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1) On September 15, 1848, William Ives set section corner post from which a 10" sugar bears S57W, 19 links and a 12" sugar N40°E, 44 links.
 - 2) USDA Form 874-9 dated 3/26/35 No corner evidence found. States corner location at road intersections.
 - 3) 1978 Gogebic County Road Commission plans for Lake Road show corner position.
 - 4) April 11, 1983 5/8" x 30" rebar at fence line intersection and road intersections extended guy pole S41°E, 43.76 feet; power pole S44°W, 48.69 feet; 8" maple N38°W, 47.16 feet. John R. Garske recorded corner in Liber 2, page 503.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found corner position as noted above and updated to county and state specifications.

P.A. 74 research on file with Register of Deeds office.

PEER GROUP APPROVED

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3/4" diameter x 30" iron rod with a 3 1/4" diameter aluminum cap stamped: County Remonumentation; T48N, R47W; S-10; S-11; S-14; S-15; 1995; RLS 28410, from which I established the following bearing trees and/or reference objects: guy pole - S41°E, 43.76 feet; power pole - S4°W, 48.69 feet; 10" sugar - N38°W, 54.66 feet; a reference object consisting of a 2 1/2" diameter x 30" long aluminum pipe with a 3 1/4" diameter aluminum cap stamped: County Remonumentation; T48N, R47W; S-10; S-11; S-15; S-14; 1995; RLS 28410; S60°W - 43.73 feet; A 6 foot steel rail with sign 1.29 feet away.

5-15, 5-14, 1995, RLS 26410, 500 W - 45.75 leet, A 0 loot steel fall with sign 1.29 leet away.

Date

FORM APPROVED BY MICHEANS JATE START OF

GARSKE LAND SURVEYOR

> MAN SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983

Fed. No. J-17