

JUN 2 9 1995

Gogebic

on this certificate.

1. Public Land Survey

2. Property Controlling

For corners in

COMMISSION

S-15

LAND	CORNER	RECORDATION	CERTIFICATE

	R RECORDATION CERTION CERTION CERTION OF Act 74, Mich. P.	• • • • • • • • • • • • • • • • • • • •
ocated In:	Corner Code ##	A B 13.95 at 1:30 states
T_48N_R 47W_ T R	I-7	Liber 5 ai Coentes
T R T R		Ramona Couring Deput
T R T R		Register of Deads Stome & File Number
T R		Register of Deeds Stamp & File Number
at		

Reciptor's Office

in Section 3. Miscellaneous Property in Sec.	Miscellaneous S T R Re			egister of Deeds Stamp & File Nu							
	Recorded Plat		- ,	В	C D	E	F	G H	1,		
	on to Sections 14, 15, 22 & 23, T48N, l		2	- 6-	5-	+	<u> </u>	-3			
I. John R. Garske	_, in a field survey onMarch 2	. 19 <u>95</u> .	4	_ }_	- 8-	\perp	- b —	-10	1		
do hereby certify that under r	equirements of P.A. 74, Michigan P.A. of 1970 in conformance with regulations and rules	0, the corner points mentioned stherefore as required in the	6	18 		+	 -16 	 15 	+		
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as			8 -	-19-	20		21	-22	1		
expressed below:			10	-30-	29	╀	2 8	27	+		
NOTE: Not more than 4	corners, all in the same town and ran	ge, may be recorded	11		1	-+-	+		-		

A. Description of original monument and accessories and/or subsequent restoration:

Located In

- On September 13, 1848, William Ives set section corner post from which a 14" Y. birch S36°W, 30 links and a 14" Y. birch -N28°E, 44 links.
- 2) USDA Form 874-9 dated 4/1/35 No corner found. States corner location at road intersections. Found cedar post with tag east, 33.0 feet.
- 1978 Gogebic County Road Commission plans for Lake Road show corner position.
- April 11, 1983 P.K. nail Post with U.S.F.S. tag west, 30.5 feet; power pole S29°E, 45.31 feet; power pole S46°W, 55.32 feet; 8" basswood - N74°W, 53.16 feet.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I accepted the corner position in the road centerline intersection as being true as it has been used in many surveys and is setting harmoniously with all area residents. The position was verified with measurements to corners north, south and west.

Record research on file with Register of Deeds.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3 1/4" diameter brass cap stamped: T48N, R47W; S-15; S-14; S-22; S-23; 1995; RLS 28410, from which I established the following bearing trees and reference objects: 8" R. maple - N59°E, 45.88 feet; post and U.S.F.S. tag - west, 30.5 feet; 8" ash -S28°E, 59.80 feet; power pole - S46°W, 55.32 feet; a reference monument consisting of a 2 1/2" diameter x 30" long aluminum 2; S-23: 1995; RLS pipe with a 3 1/4" aluminum cap stamped: County Remonumentation; T48N, R47W; R.M.; S-15; S-14; S-22; 28410; S51°E, 48.74 feet; 6 foot steel rail with sign - 1.29 feet away.

Signed by Surveyor's Michigan License No.

28410

JOHN R. garske LAND SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARS

REVISED MAY 14, 1975 REVISED JAN., 1983