## SURVEY & , REMONUMENTATION

|--|

COMMISSION	CO	M	M	55	101
------------	----	---	---	----	-----

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Ast 74 Mish D.A. 1070

Register's Office ss.

Par agreeus to	t um & rieda	mement of Act 74, Mich. P.A	r 1910
For corners in			Received for record the
Gogebic	Located In:	Corner Code ##	10 TH day of June
(County)		33	•
	( Cat   Car	** "	A. D. 1996 at 9:40 o'clock
<ol> <li>Public Land Survey</li> </ol>	T48N R47W	<u>K-5</u>	An., and recorded in
	T R		Liber 5 of CORNERS
	T R		
	T R		m page 358
2. Property Controlling	S T R		Kamona Collins, Depuly
in Section	S T R		Register of Deeds
<ol><li>Miscellaneous</li></ol>	S R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		Tregister of Deeds Stamp & File Number
4 Lot No	Recorded Plat		
5 Private Claims	riccorded riat		A B C D E F G H I J K L J
do hereby certify that under rein lines 1 and 2 above were in current manual of survey instributions and a decree of above were in conformance with the survey in the surv	in conformance with regulations a ructions of the United States Depa a Court of Lawand/or that the corr ith the rules of the Michigan Board		the 18 17 16 15 14 13 15 14 13 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4 of	corners, all in the same town a	and range, may be recorded	11 25 25 27 26 25
on this certificate.		<u> </u>	12 31 32 33 34 35 36
			13
A. Description of original	monument and accessories ar	nd/or subsequent restoration:	
Original corner	established by Wi	Illiam Ives on Sept	. 12, 1848. Set post.

Y. Birch 18" N 250 E Hemlock 16" S 370 W Original bearing trees: 48 links

In 1992 Robert Mick, P.S. set a 3/8" by 24" rebar with yellow Cap No. L.S. 16936 at location of 3" by 3" cedar post along side a Keweenaw Land Assoc. Limited tag. He recoded said Section corner in Liber 4 on Page 90 of Land Corners for Gogebic County, He established the following bearing trees and reference objects. 13" Maple- S 05° W- 1.98'; 4" Maple- S 60° E-21.82'; 5" Maple- N 67° E- 5.85'; 4" Maple- N 06° E- 29.44'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: I found the 3/8" rebar with yellow cap No. L.S. 16936 set by Robert Mick. It checked with Mick witnesses. I updated the corner monument and accessories as noted below to state and county specification.

Act 74 reseach on file.

REPAIRSENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replace the 3/8" rebar with a  $2\frac{1}{2}$ " by 30" aluminum pipe with a  $3\frac{1}{4}$ " aluminum cap stamped: County Remonumentation; S-11, S-12, S-13, S-14; 1996, P.S. 23509. I established the following bearing trees and reference objects.

14"	Maple	S	05 <sup>0</sup> W	1.981
4"	Elm	S	60° E	21.821
	Maple		67° E	5.851
6"	Maple	N	06 <sup>0</sup> E	29.44
61	Rail & sign	N	240 W	2.731
61	Rail & sign	N	240 W	2.73

Signed by John P Yous

Date May

GOSS SURVEYOR 23509

REVISED JAN . 1983

21,1996

Surveyor's Michigan License No. Fed. No. J-21