	,				Gogebic County ss.						
	LAND CORNER RECORDATION CERTIFICATE			Renic		-)					
For corners in Filing Requirement of Act 74, Mich. P.A. 1970					Received for record the day of August						
Gogebic (County)	Located In:	Corner Code ##				.at _ /:					
1. Public Land Survey S-	T 47N R 47W T R 47W T 48M R 47W	L-13	Lil en	liber 5 of Corners on page 73 Kamona Column, Occuty							
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R		Register			Regist	er o	f Beed	is T		
	ecorded Plat		, <u>A</u>	в с	D 1	E F G	<u> </u>	1 J K	C L N		
		May 5 94	3	1	- 8	9			12		
do hereby certify that under requirements 1 and 2 above were in current manual of survey instructionagement or by a decree of a above were in conformance with	in a field survey onuirements of P.A. 74, Michigan P.A. of conformance with regulations and ctions of the United States Departm Court of Law and/or that the corner partners as the rules of the Michigan Board of Leestablished, monumented, re-mo	1970, the corner points mentione rules therefore as required in the ent of the Interior, Bureau of Landoints mentioned in lines 3, 4 and and Surveyors or by a Decree of	d 6 7 5 8 a	-18	-17	21 28	-15 -22 -27	23-26-	24-25-		
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.				31	32	33	-34	35—	36-		
	nonument and accessories and/o		13			.					

Original survey by William Austin Burt in 1847, set Ironwood post. Original Bearing Trees:

Sugar 5" - N41'E - 29 links Hemlock 6" - N46°W - 4 links

U.S.D.A. survey in 1938. Set a 5" x 42" concrete monument with stamped bronze cap. Chiseled "X"s in bedrock as witnesses.

Survey by John R. Garske, RLS 28410, in August of 1988. Found chiseled "X"s from U.S.D.A. survey. Reestablished corner position from these witnesses. Corner position matches GLO calls. Recorded in Liber 3 of Land Corners on page 253 by J. Garske.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" x 30" rebar with aluminum stamped cap with stone pile around it. Remonumented the corner position and updated the accessories as noted below to bring them up to state and county specifications. Corner accessories by Garske in good condition and are noted again below.

Act 74 research on file with County Register of Deeds Office.

PEER GROUP

Approved

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 5/8" rebar with a 3/4" x 30" long rebar with a 3" aluminum cap stamped: County Monumentation, T48N, R47W, T47N, 1/4, S-36, S-1, 1994, RLS 28410, from which I established the following accessories: (shallow bedrock in area did not allow a standard aluminum monument)

4" ash - S44°E - 52.76 feet 4" ash - N11°W - 7.76 feet

3" ash - Due East - 21.74 feet

6" Ironwood - S55°W - 10.14 feet

JOHN R. GARSKE LAND SURVEYOR No. 28410

Signed by

Surveyor's Mich/gan License No.

REVISED MAY 14, 1975 REVISED JAN., 1983