SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's wifice sa.

1 of collers ill				1
Gogebic (County)	Located In:	Corner	Code#	
1. Public Land Survey	T48 ^N R T R	46 ^W	A-5	R. J. N. 1/21/99
Property Controlling in Section Miscellaneous Property in Sec.	ST_R ST_R ST_R ST_R		м-3	1/2/199

Received for record the

2157 day of July

A. D. 1999 at 1:25 o'clock

m., and recorded in

Liber 7 of Corners


Register of Beads

Register of Deeds Stamp & File Number

4. Lot No 5. Private Cla	orded Plat					
Section	corner	7,18,12	&	13	T48N,	R46-47W

I, <u>John P. Goss</u>, in a field survey on <u>May 15</u>, 19 <u>99</u>do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



E OF MICHIGAN

LAND SURVEYOR

23509 EPEO LAND

A Description of original monument and accessories and/or subsequent restoration:
Corner established by William Burt, U.S. Deputy Surveyor, in September, 1847.
Original bearing trees: W. Pine 24" N 72° E 24 links (15.84'); Hemlock 10"
West 9 links (5.94'); Maple 10" S 34° E 35 links (23.10'); Hemlock 20"
N 22° W 32 links (21.12').
On May 22, 1975, Richard L. Drahn, RLS, found corner position marked by a 2"x2"

board at recorded bearing and distance from the remains of four original bearing trees: He set a 22" iron pipe with 3" cap, stamped to indicated the corner position. He established the following reference objects:

9" Cedar N 090 W 30.31; 12" Hemlock S 210 E 29.41;

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

5" Cedar S 76° W 20.6': 7' Metal sign post S 32° W 2.5'.

He recorded said corner in Liber 1, page 173 of Land Corners for Gogebic Co.

Found Richard L. Drahn, monument and accessories.

Found 38" White pine stump with G.L.O. Blaze.

I updated the monument and accessories as noted below to state and county specification.

Act 74 research on file.

Richard L. Drahn 7/20/99

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From found monument I established the following new and existing reference objects:

15" 7" 9"	Cedar Hemlock Cedar Cedar	2 2 7	5	09° 21° 76° 67°	E W E	30.12 29.32 20.61 10.49	ft. ft. ft.		
י7	Metal sign	post S		320		2.5		to	face

(All distance to nail in side of tree)

Date May 15, 1999

Signed by John P Hospital Surveyor's Michigan License No.

23509 U.S.F.S. No. J-1