SURVEY & REMONUMENTATION

OCT 0 3 1996

For corners in

Property in Sec.

Lot No. __

COMMISSION

_____, Recorded Plat _

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

register's ()[110	e
Gogebic Count	y } Ss.
Receive	ed for record the
1619 d	y of <u>Cornary</u>
A. D. 19 96 1	t 10:30 o'clock
<u>A</u> m.	and recorded in
	of CONNERS
PM 400	†
Ramom Co	Lino Deputy Rogister of Dood
Ī	legister of Docas

Gogebic Corner Code ≠# Located In: T 48N R 47W 1. Public Land Survey 1 48N R 48W 2. Property Controlling _ r _ 3. Miscellaneous _ T .____ R .

Register of Deeds Stamp & File Number

) .	Private Claim Section			18;	T.48	N.,	R.47-48 W.	
lo	hereby certify th	at under requ	irements of P.A. 74,	Michiga	an P.A. of 1	970, the	, 19 <u>96</u> , ecorner points mentioned erefore as required in the	

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William Burt, in 1847. Original bearing trees 1. Spurce 9" N 18° E 40 1i 2. Hemlock 16" S 47° W 23 1i

40 links (26.40') 23 links (15.18')

2. Hemlock 16" S 47° W 23 links (15.18')
3. Hemlock 14" S 68° E 55 links (36.30')
4. Spurce 8" N 62° E 31 links (20.46')
Richard L. Drahn & John P. Goss, both R.L.S. restored the corner position at record bearing and distance from the remains of the original bearing trees. At the corner position they set a 1½" I.D. by 4 foot long, concrete filled, iron pipe, capped with a 3" circular brass table which reads:
T.48 N., R.47-48 N.; S-12, S-13, S-7, S-18; 1978; R.L.S. 23509. From which Description of corner evidence found and/or method applied in restoring or reestablishing corner:
they established the following new blazed and scribed bearing trees:

they established the following new blazed and scribed bearing trees:

10" Hemlock

0" Hemlook N. 120 W. 20.6' 2" Hemlook S. 88° E. 28.0' 3" Red Maple S. 42° W 26.6' 12" Hemlock recorded said corner in Liber 1 on pages 402 and 403 of Land Corners for Gogebic

County.

I found the lim I.D., iron pipe with 3" Circular brass table and it checked with Drahn and Goss witnesses. I updated the accessories as noted below to state and county spec ification. All of the evidence found in 1978 survey still at this location. Act 74 research on file.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the lin iron pipe with 3" brass table, I established the following existing and new bearing trees and reference objects.

N 120 W 20.60 14" Hemlock S 88° E S 42° W N 56° E 16" Hemlock 28.01 4" Red Maple 27.64 6" Hemlock 7.881 N 030 W 1.12! 6 rail & sign



Bigned by John Ploso Burveyor's Michigan License No. _

23509 Fed No. J-1 & J-25