FEB 1 8 1994

()	à B	10	1	000	F- 1	١.
1 2 4	118	117	8. 5	. 3	(";	١,

Register' Gogebic	S	Üſ	hee)
Gogebic	ŧ	OU	nty	88

COMMISSION	LAND COR	NER RECORDATION CERTIF	ICATE		•)		
For corners in	Filing Requ	irement of Act 74, Mich. P.A	l. 1970	Heceiv		record th	
Gogebic	Located In:	0). 19 <i>93</i>			
(County)	Cocarco III,	Corner Code ±#					
1. Public Land Survey Section	n 11 _T 48N n 49W	K-4		<i>P</i> m, r4			
•	TR					AUK WE	Rao P
	T R			kege_346		. •	4.
	TR		-1/14	Thy I			ity
2. Property Controlling S	T R			0	Register	AR BREE	ds/
	<u>T</u> <u>R</u>						
3. Miscellaneous S Property in Sec. S	T R		Register of D	eeds Stam	ın & File	Number	•
Troperty in Sec. S	T R						<u> </u>
4. Lot No, Recorde	d Plat						
5. Private Claims			—— <u>А в</u>	CDE	F G H	I J K	L M
One-quarter corner	Section 11 & 12.		2 - 6	├─ \$ ├ - \$		╀┇╌┼	- -
			3	┞╼╂╼╂┈╂		╂╌╂╌╂	- -
John R. Garske , in a fi	ield survey on	December 6 93	4}	┝╌┇╌┼╌┆		 ¦∳-	- 12-
no verena cerma mar namer tednitelbet	IIS OF P.A. 74. Michigan P.	A 011970 the corner points montion	act III	┝╼╂╾╂┈╂	╼┼╼┼╼	╂╌╂╼╂╸	_
in lines I and 2 above were in confort	mance with regulations a	and rules therefore as required in t	ha [□] 18	1716	15	1-14	{3
current manual of survey instructions of Management or by a decree of a Court of	n the United States Departured I Law and/or that the com	artment of the Interior, Bureau of La	nd 7			╂╼╂╼╂	
above were in conformance with the rul	les of the Michigan Board	l of Land Surveyors or by a Docrop o		-2021		23	24
Court of Law; established, re-estable expressed below;	ished, monumented, re	-monumented, recovered, found	as 9	- - - 		╁┈┼╼┼╴	
	all in the same taken		10 30	2928	-27	26	-25-
NOTE: Not more than 4 corners, on this certificate.	an in the same town a	and range, may be recorded	11			╂╼┼╼╁╌	+
Title Gartineard,			12 -31	-3233	34-	35	-36
A. Description of original monume	ent and accessories ar	7d/Or subsequent restoration:	13 [

Original survey by William Ives, Deputy Surveyor, on August 11, 1848. Set quarter section post (north to south). Bearing trees:

5" cedar - N61°W - 16 links 6" Y. birch - S32°E - 23 links

No original evidence found.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established the one-quarter corner by single proportional measurement between opposing section corners on line and one-half the distance in accordance with the original government survey notes.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Bernsten 2 1/2" aluminum pipe with 3 1/2" Remonumentation; T48N, R49W; 1/4 cor.; S-11; S-12; following bearing trees and reference objects:	aluminum cap stamped: County 1993; RLS 28410. Established the
	111 200

Power pole L.S.D.P. #11-93/51 - N81°W - 61.78 feet 7" H. maple - N89°E - 39.66 feet Steel sign post - S-47°E - 1.44 feet
10" White Birch - 5.06°W - 15.81 FREE
CL. of Powers Rono - West 29 Free

GARSKÜ LAND SURVEYOR

Surveyor's Michigan License No.